





### General information

Make	PEUGEOT
Model	HORIZON E-HDI TEPEE S
Colour	Silver
Year of manufacture	2014
Top speed	103 mph
0 - 60 mph	14.3 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	58.9 mpg
CO2 emission	115 g/km
CO2 label	С







### Internet history

Entry 2

Date

Pictures

2023-12-11

9



source: g3remarketing.co.uk

Entry 1	
Date	2022-01-17
Pictures	52
Listing price	<u>View report</u>



source: autotrader.co.uk









# MOT history

MOT expiry date	2025-02-01
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	18
Total items failed	6

MOT #12	2024-02-02 14:15
MOT test number	212008786602
Result	✓ Passed
Next expiry date	2025-02-01
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	



SF14FDN	
report date: 2024-03-2	28

MOT #11	2024-02-01 16:03
MOT test number	817274594775
Result	🗙 Failed
<b>Fail</b> Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Fail Electronic stability control warning lamp indicates a fault (7.12 (e))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both fronts	s (1.1.14 (a) (ii))
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Items removed from driver's view prior to test	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	

MOT #10	2023-01-31 12:17
MOT test number	821687560090
Result	✓ Passed
МОТ #9	2022-01-17 12:15
MOT test number	492800270604
Result	✓ Passed
МОТ #8	2020-11-17 15:29
MOT test number	823411919226

Result

🗸 Passed





MOT #7	2020-11-17 10:54
MOT test number	149064925846
Result	🗙 Failed
<b>Fail</b> Nearside Front Drive shaft joint constant velocity boot split or insecure, no ingress of dirt (6.1.7 (g) (ii))	o longer prevents the
MOT #6	2019-11-13 12:10
MOT test number	156609017951
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Both rear tyres cracking at sidewall

MOT #5	2018-12-24 15:13
MOT test number	153511787273
Result	✓ Passed

MOT #4	2018-12-19 17:23
MOT test number	978282459011
Result	🗙 Failed
Advice Exhaust centre clamp corroded	
<b>Fail</b> Offside Front Drive shaft joint constant velocity boot split or insecure, no lo	nger prevents the ingress

of dirt (6.1.7 (g) (ii))

MOT #3	2018-02-27 14:03
MOT test number	353607315632
Result	✓ Passed
Advice Under tray fitted covering underside components.	





739674342155

🗸 Passed

MOT #2	2018-02-23 13:05
MOT test number	690756884120
Result	🗙 Failed
FailWindscreen washer provides insufficient washer liquid (8.2.3)AdviceUnder tray fitted covering underside components.	
MOT #1	2017-06-28 09:07

#### MOT test number

Result	
Advice	Under tray fitted covering underside components.



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	✓ MOT Expires: 1 February 2025
Tax status	Valid until 1 February
Days left	279
MOT expiry date	1 February 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
*******	
******	
*********	
********	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plata since	





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-07-23
Last registration	2024-02-02
Complete history	See info



Registration #1	2014-07-23	23 mi
Registration #2	2017-06-28	8.513 mi
Registration #3	2018-02-23	9.996 mi
Registration #4	2018-02-27	9.996 mi
Registration #5	2018-12-19	12.427 mi
Registration #6	2018-12-24	12.487 mi
Registration #7	2019-11-13	16.291 mi
Registration #8		11.777 est
Registration #9		11.777 est
Registration #10		11.777 est
Registration #11		10.100 est
Registration #12		11.777 est
Registration #12 Registration #13		11.577 est 11.577 est





### Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	87%
Pedestrian	41%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1624 kg
Max. allowed weight	2070 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	JBFR0011415