



UK

SKIIVKJ

report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | FIAT           |
| Model               | PUNTO GP       |
| Colour              | Blue           |
| Year of manufacture | -              |
| Top speed           | 103 mph        |
| 0 - 60 mph          | 13.2 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption


|                         |                     |
|-------------------------|---------------------|
| Power                   | 77 BHP              |
| Max. torque             | 115 Nm at 3.250 rpm |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 38.2 mpg            |
| Consumption extra urban | 60.1 mpg            |
| Consumption combined    | 49.6 mpg            |





Internet history


Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-02                  |
| Pictures      | 11                          |
| Listing price | <a href="#">View report</a> |









source: autotrader.co.uk

**MOT history**

|                         |  |
|-------------------------|--|
| <b>MOT #14</b>          | 2022-09-01 10:03                                   |
| <b>MOT test number</b>  | 245675130915                                       |
| <b>Result</b>           | ✓ Passed   |
| <b>Next expiry date</b> | 2023-09-06   |
| <b>Advice</b>           | Offside Rear Coil spring corroded (5.3.1 (b) (i))  |
| <b>Advice</b>           | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) |

|                        |                  |
|------------------------|------------------|
| <b>MOT #13</b>         | 2021-09-07 10:45 |
| <b>MOT test number</b> | 927315645037     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #12</b>         | 2021-03-24 10:28 |
| <b>MOT test number</b> | 184989784662     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #11</b>         | 2020-03-18 10:38 |
| <b>MOT test number</b> | 766384932738     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #10</b>         | 2019-03-26 14:48 |
| <b>MOT test number</b> | 659035310765     |
| <b>Result</b>          | ✓ Passed         |

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

|                        |                  |
|------------------------|------------------|
| <b>MOT #9</b>          | 2018-02-24 08:52 |
| <b>MOT test number</b> | 440834471702     |
| <b>Result</b>          | ✓ Passed         |

**MOT #8** 2018-02-24 08:52**MOT test number** 301761651358**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #7** 2017-02-24 17:27**MOT test number** 615026648341**Result** ✓ Passed**MOT #6** 2016-09-27 10:54**MOT test number** 930044262064**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases down pipe seal (7.1.2)**Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #5** 2016-09-27 10:54**MOT test number** 928154324765**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases down pipe seal (7.1.2)

**MOT #4** 2015-09-30 11:54**MOT test number** 421790400375**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-10-18 13:38**MOT test number** 929651094269**Result** ✓ Passed**MOT #2** 2014-04-17 09:45**MOT test number** 235557404120**Result** ✓ Passed**Notice** Clutch Pedal Anti Slip Damaged**Notice** Front Fog Light Operative When Using Directional Indicators**Advice** Seat belt stitching slightly frayed (5.2.2b)**Notice** Nail in offside rear tyre**Notice** Drivers Seat Frayed



MOT #12014-04-17 09:45

MOT test number305257304120

Result

Failed

- NoticeClutch Pedal Anti Slip Damaged
- NoticeFront Fog Light Operative When Using Directional Indicators
- Pass with rectificationRegistration plate insecure (6.3.1b)
- NoticeNail in offside rear tyre
- NoticeDrivers Seat Frayed
- AdviceSeat belt stitching slightly frayed (5.2.2b)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |            |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this FIAT had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2024-03-29 |
| Current registration |            |
| Plate since          | 2024-03-29 |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 15                       |
| First mileage registration | 2011-03-31               |
| Last registration          | 2022-09-01               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2011-03-31 | 24 mi      |
| Registration #2  | 2014-04-17 | 29.772 mi  |
| Registration #3  | 2014-10-18 | 33.724 mi  |
| Registration #4  | 2015-09-30 | 43.396 mi  |
| Registration #5  | 2016-09-27 | 33.124 mi  |
| Registration #6  | 2016-09-27 | 33.124 mi  |
| Registration #7  | 2017-02-24 | 55.175 mi  |
| Registration #8  | 2018-02-24 | 602.836 mi |
| Registration #9  | 2019-05-29 | 25.277 mi  |
| Registration #10 | 2019-05-29 | 25.277 mi  |
| Registration #11 | 2019-05-29 | 25.277 mi  |
| Registration #12 | 2019-05-29 | 25.277 mi  |
| Registration #13 | 2019-05-29 | 25.277 mi  |
| Registration #14 | 2019-05-29 | 25.277 mi  |
| Registration #15 | 2019-05-29 | 25.277 mi  |

More info >



Car features

The FIAT factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1687 mm |
| Height              | 1490 mm |
| Length              | 4065 mm |
| Wheel base          | 2510 mm |
| Kerb weight         | 1040 kg |
| Max. allowed weight | 1600 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |

|                        |         |
|------------------------|---------|
| <b>Number of axles</b> | 2       |
| <b>Engine number</b>   | 6332630 |