



report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 260 SWB LR P/V 85
Colour	Black
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2023-08-08
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	34
Total items failed	20

MOT #14 2022-08-09 16:27

MOT test number 702452503668

Result ✓ Passed

Next expiry date 2023-08-08

- Advice** Central Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Non obligatory mirror damaged slight crack
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13 2021-07-02 13:23

MOT test number 963991905214

Result ✓ Passed

- Advice** Suspension component mounting repair covered in underseal n/s rear inner sill (5.3.6 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material n/s and o/s front (1.1.11 (c))

**MOT #12**

2021-07-01 11:07

MOT test number

778460452935

Result**✗ Failed****Fail** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))**Advice** Brake pipe corroded, covered in grease or other material n/s and o/s front (1.1.11 (c))**Fail** Suspension component mounting prescribed area excessively corroded significantly reducing structural strength n/s rear inner sill (5.3.6 (a) (i))**Fail** Windscreen washer not working (3.5 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11**

2020-06-25 09:11

MOT test number

625149443257

Result**✓ Passed****Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))**Advice** Outer sill corroded**MOT #10**

2019-03-09 11:59

MOT test number

821335375821

Result**✓ Passed****MOT #9**

2019-03-08 17:34

MOT test number

121364940310

Result**✗ Failed****Minor** Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #8** 2018-03-12 16:53**MOT test number** 876904190480**Result** ✓ Passed**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #7** 2018-03-08 10:21**MOT test number** 394208015145**Result** ✗ Failed**Fail** Offside Rear brake caliper leaking (3.6.A.1)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Fail** Offside Obligatory mirror seriously deteriorated, affecting the rear view (8.1.2a)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Driver's seat insecure (6.2.A.1)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Nearside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Advice** Drivers seat base collapsed**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #6** 2017-03-14 10:10**MOT test number** 370446389365**Result** ✓ Passed

**MOT #5**

2017-03-13 13:20

MOT test number

451899151100

Result**✗ Failed**

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Front Headlamp aim too low (1.8)
- Fail** Nearside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front Headlamp aim too high (1.8)
- Fail** Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

MOT #4

2016-04-16 08:30

MOT test number

165025525894

Result**✓ Passed**

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Sump Leaking Oil
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2015-03-02 12:31**MOT test number** 857751865002**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2015-03-02 12:31**MOT test number** 759831265048**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #1** 2013-12-27 12:43**MOT test number** 697221163306**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 November 2022

✕
MOT

Expired:
8 August 2023

Tax status	Expired at 1 November 2022
Days left	544 days too late
MOT expiry date	8 August 2023
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-12-31
Last registration	2022-08-09
Complete history	See info



Registration #1	2010-12-31	29 mi
Registration #2	2013-12-27	80.398 mi
Registration #3	2015-03-02	94.030 mi
Registration #4	2016-04-16	106.185 mi
Registration #5	2017-03-13	120.044 mi
Registration #6	2017-03-14	120.047 mi
Registration #7	2018-03-08	139.678 mi
Registration #8	2019-03-09	151.277 mi
Registration #9	2019-03-09	151.277 mi
Registration #10	2019-03-09	151.277 mi
Registration #11	2019-03-09	151.277 mi
Registration #12	2019-03-09	151.277 mi
Registration #13	2019-03-09	151.277 mi
Registration #14	2019-03-09	151.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2374 mm
Height	1997 mm
Length	4863 mm
Kerb weight	1580 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	AG87451