



**NVI4NVW**

report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 DSTYLE
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-07-30
Pictures	35
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-29
Pictures	35
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-15
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	22
Total items failed	6

MOT #10	2023-09-15 10:55
MOT test number	660686515517
Result	✓ Passed
Next expiry date	2024-09-15
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2023-09-08 09:45
MOT test number	544345218639
Result	✗ Failed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Brake pad(s) wearing thin all (1.1.13 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2022-09-16 09:00**MOT test number** 505816947137**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2022-09-15 15:10**MOT test number** 108301231827**Result** ✗ Failed**Minor** Offside Windscreen wiper blade defective worn (3.4 (b) (i))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #6** 2021-08-26 11:30**MOT test number** 288546678237**Result** ✓ Passed**MOT #5** 2021-02-11 17:22**MOT test number** 590726705865**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #4** 2020-02-11 14:53**MOT test number** 421677959585**Result** ✓ Passed

**MOT #3** 2019-01-02 14:49**MOT test number** 897635657334**Result** ✓ Passed**Advice** Front discs & brake pads worn.**Advice** Engine covers & under trays fitted.**MOT #2** 2019-01-02 14:49**MOT test number** 153203086226**Result** ✗ Failed**Advice** Front discs & brake pads worn.**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Engine covers & under trays fitted.**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #1** 2017-12-04 17:00**MOT test number** 617752936479**Result** ✓ Passed**Advice** Rear Parking brake lever has little reserve travel (3.1.6b)**Advice** Rear Lower Exhaust has a minor leak of exhaust gases exhaust bracket broken but still serviceable (7.1.2)**Advice** Front Brake pad(s) wearing thin both n/s o/s (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
15 September 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	15 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-06-09
Last registration	2023-09-15
Complete history	<a href="#">See info</a>



Registration #1	2014-06-09	16 mi
Registration #2	2017-12-04	24.521 mi
Registration #3	2019-01-02	29.645 mi
Registration #4	2019-01-02	29.645 mi
Registration #5	2020-02-11	32.496 mi
Registration #6	2021-02-11	34.164 mi
Registration #7	2023-09-15	35.277 mi
Registration #8	2023-09-15	35.277 mi
Registration #9	2023-09-15	35.277 mi
Registration #10	2023-09-15	35.277 mi
Registration #11	2023-09-15	35.277 mi
Registration #12	2023-09-15	35.277 mi
Registration #13	2023-09-15	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1075 kg
Max. allowed weight	1554 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA2082498