



PKI3SK0

report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ
Colour	Blue
Year of manufacture	2013
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





MOT history

MOT expiry date	2024-07-18
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	29
Total items failed	1

MOT #112023-07-19 12:56

MOT test number288911876149

Result✓ Passed

Next expiry date2024-07-18

- Minor

Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Nearside Brake pipe corroded, covered in grease or other material front to rear to flexi (1.1.11 (c))
- Advice

Offside Front Coil spring modified but not seriously weakened (5.3.1 (d) (i))
- Minor

Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material to cylinder (1.1.11 (c))
- Advice

Nearside Front Coil spring modified but not seriously weakened (5.3.1 (d) (i))
- Advice

Central Front Exhaust has a minor leak of exhaust gases flange (6.1.2 (a))
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material to cylinder (1.1.11 (c))

**MOT #10**

2023-07-17 10:57

MOT test number

405729995909

Result

✗ Failed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to cylinder (1.1.11 (c))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear to flexi (1.1.11 (c))
- Advice** Offside Front Coil spring modified but not seriously weakened (5.3.1 (d) (i))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Offside Brake pipe excessively corroded front to rear to flexi (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to cylinder (1.1.11 (c))
- Advice** Nearside Front Coil spring modified but not seriously weakened (5.3.1 (d) (i))
- Advice** Central Front Exhaust has a minor leak of exhaust gases flange (6.1.2 (a))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn wishbone (5.3.4 (a) (i))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #9

2022-01-21 18:01

MOT test number

605772176780

Result

✓ Passed

MOT #8

2021-02-23 15:35

MOT test number

814719061515

Result

✓ Passed

MOT #7

2020-02-03 14:50

MOT test number

958627740763

Result

✓ Passed

- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #6** 2019-05-22 08:56**MOT test number** 830247787976**Result** ✓ Passed**MOT #5** 2019-05-21 10:06**MOT test number** 894924923242**Result** ✗ Failed

DANGEROUS Offside Front Brake disc in such a condition that it is seriously weakened Disc warped (1.1.14 (a) (ii))

MAJOR Offside Front Suspension component pin or bush excessively worn rear bush (5.3.4 (a) (i))

DANGEROUS Nearside Front Brake disc in such a condition that it is seriously weakened Disc warped (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #4 2018-05-30 08:55**MOT test number** 509155409578**Result** ✓ Passed**MOT #3** 2017-06-02 10:16**MOT test number** 623532075955**Result** ✓ Passed

Advice Offside Front approaching tread wear indicators

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2017-06-02 10:16
MOT test number	286014510524
Result	✗ Failed
Advice	Offside Front approaching tread wear indicators
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Rear registration plate insecure (6.3.1b)

MOT #1	2016-05-13 08:22
MOT test number	775822779549
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
18 July 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	18 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	PK13SKO
Plate since	2019-03-29
Current registration	PK13SKO
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-05-30
Last registration	2023-07-19
Complete history	See info



Registration #1	2013-05-30	16 mi
Registration #2	2016-05-13	27.409 mi
Registration #3	2017-06-02	35.209 mi
Registration #4	2017-06-02	35.209 mi
Registration #5	2018-05-30	42.918 mi
Registration #6	2019-05-21	50.143 mi
Registration #7	2019-05-21	50.143 mi
Registration #8	2019-05-21	50.143 mi
Registration #9	2019-05-21	50.143 mi
Registration #10	2019-05-21	50.143 mi
Registration #11	2019-05-21	50.143 mi
Registration #12	2019-05-21	50.143 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1630054