



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	White
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-09-10
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

Entry 1

Date	2021-09-04
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://autotrader.co.uk)



MOT history

MOT expiry date	2025-04-24
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	18
Total items failed	9

MOT #13	2024-04-25 15:22
MOT test number	141340722486
Result	✓ Passed
Next expiry date	2025-04-24
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2024-04-25 13:01
MOT test number	903296130760
Result	✗ Failed
Fail	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #11**

2022-10-21 16:25

**MOT test number**

900016607128

**Result**

✓ Passed

**Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Minor**

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10**

2022-10-21 16:25

**MOT test number**

268674228847

**Result**

✗ Failed

**Advice**

Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Pass with rectification**

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Minor**

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9**

2021-10-14 07:31

**MOT test number**

308873355091

**Result**

✓ Passed

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2020-11-28 11:19

**MOT test number**

930892567153

**Result**

✓ Passed

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2020-11-28 11:19**MOT test number** 980774884423**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-11-30 10:01**MOT test number** 920422448586**Result** ✓ Passed**MOT #5** 2019-11-30 10:01**MOT test number** 714104196836**Result** ✗ Failed**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #4** 2018-11-29 18:02**MOT test number** 462820773191**Result** ✓ Passed**Advice** Offside Front tyre very badly worn on inside edge**Advice** Front Brake disc worn, but not excessively both discs (1.1.14 (a) (i))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #3** 2017-12-02 12:56**MOT test number** 672422572100**Result** ✓ Passed



MOT #2	2016-12-02 16:53
MOT test number	794349249179
Result	✓ Passed
Advice	Engine cover fitted
Advice	Under trays fitted

MOT #1	2016-02-08 12:41
MOT test number	263544013417
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2024

✓

MOT

Expires:  
24 April 2025

Tax status	Expired at 1 April 2024
Days left	28 days too late
MOT expiry date	24 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>EU13VTK</b>
Plate since	2019-06-29
Current registration	<b>EU13VTK</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-03-27
Last registration	2024-04-25
Complete history	<a href="#">See info</a>



Registration #1	2013-03-27	22 mi
Registration #2	2016-02-08	18.385 mi
Registration #3	2016-12-02	23.174 mi
Registration #4	2017-12-02	38.697 mi
Registration #5	2018-11-29	48.187 mi
Registration #6	2019-11-30	55.706 mi
Registration #7	2019-11-30	55.706 mi
Registration #8	2020-11-28	58.550 mi
Registration #9	2020-11-28	58.550 mi
Registration #10	2020-11-28	58.550 mi
Registration #11	2020-11-28	58.550 mi
Registration #12	2020-11-28	58.550 mi
Registration #13	2020-11-28	58.550 mi
Registration #14	2020-11-28	58.550 mi
Registration #15	2020-11-28	58.550 mi
Registration #16	2020-11-28	58.550 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ