



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	FR-V VTEC SPORT
Colour	Black
Year of manufacture	2006
Top speed	120 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.6 mpg
CO2 emission	199 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-05-28
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-04
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	16
Total items failed	5

MOT #17 2023-05-05 10:00

MOT test number 241536466016

Result ✓ Passed

Next expiry date 2024-05-04

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #16 2022-03-30 10:37

MOT test number 260241625213

Result ✓ Passed

Advice Front pads low . under tray fitted to the car all round

MOT #15 2021-02-22 13:08

MOT test number 926106395306

Result ✓ Passed

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #14**

2021-02-19 10:34

MOT test number

280178068648

Result

✗ Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #13**

2020-02-20 18:24

MOT test number

170770633051

Result

✓ Passed

Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))**MOT #12**

2019-02-19 14:25

MOT test number

895145436999

Result

✓ Passed

MOT #11

2018-02-19 13:25

MOT test number

465629520867

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2018-02-16 10:32**MOT test number** 520952099564**Result** ✗ Failed**Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Anti-roll bar has excessive play in a ball joint adrift (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2017-02-14 10:32**MOT test number** 401846342044**Result** ✓ Passed**MOT #8** 2016-02-24 11:50**MOT test number** 263701027345**Result** ✓ Passed**MOT #7** 2015-02-23 12:03**MOT test number** 196364455069**Result** ✓ Passed**MOT #6** 2014-02-14 15:01**MOT test number** 109705944410**Result** ✓ Passed**MOT #5** 2013-02-19 11:06**MOT test number** 297990353065**Result** ✓ Passed



MOT #4	2012-02-06 11:55
--------	------------------

MOT test number	418377232090
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #3	2011-02-01 11:11
--------	------------------

MOT test number	468902231032
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #2	2010-02-15 14:15
--------	------------------

MOT test number	731866940033
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #1	2009-02-06 10:27
--------	------------------

MOT test number	484697439040
-----------------	--------------

Result	✓ Passed
--------	----------



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
4 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	4 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-02-24
Last registration	2023-05-05
Complete history	See info



Registration #1	2006-02-24	18 mi
Registration #2	2009-02-06	15.819 mi
Registration #3	2010-02-15	21.941 mi
Registration #4	2011-02-01	28.558 mi
Registration #5	2012-02-06	35.841 mi
Registration #6	2013-02-19	41.633 mi
Registration #7	2014-02-14	49.004 mi
Registration #8	2015-02-23	54.301 mi
Registration #9	2016-02-24	60.312 mi
Registration #10	2017-02-14	65.595 mi
Registration #11	2018-05-22	70.377 mi
Registration #12	2019-05-22	75.377 mi
Registration #13	2020-05-22	80.377 mi
Registration #14	2021-05-22	85.377 mi
Registration #15	2022-05-22	90.377 mi
Registration #16	2023-05-22	95.377 mi
Registration #17	2024-05-22	100.377 mi
Registration #18	2025-05-22	105.377 mi
Registration #19	2026-05-22	110.377 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1447 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Engine number	K20A92003809