





report date: 2024-03-29

## General information

Make	FIAT
Model	TIPO EASY PLUS
Colour	Black
Year of manufacture	2017
Top speed	115 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	94 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

#### Entry 2

Date 2021-09-07

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

 Date
 2021-09-06

 Pictures
 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-07
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	10
Total items failed	6

MOT #8	2023-11-04 14:06
MOT test number	417190040008
Result	✓ Passed
Next expiry date	2024-11-07
Advice Front Play in steering rack inner joint(s) both front slight play	

MOT #7		2023-11-04 14:06
MOT test number		346861396196
Result		<b>X</b> Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))	
Advice Front Play in steering rack inner joint(s) both front slight play		

MOT #6	2022-11-08 15:46
MOT test number	621624864553
Result	<b>✓</b> Passed
Minor Battery insecure but not likely to fall from carrier Strap screw missing (4.13 (  Advice Rear Brake disc worn, but not excessively Corroded and scored (1.1.14 (a) (	

CarCheck.co.uk page 3/12



MOT #5 2022-11-05 15:32

**MOT test number** 720211214231

Result X Failed

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Rear Brake disc worn, but not excessively Corroded and scored (1.1.14 (a) (i))

Fail Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))

Minor Battery insecure but not likely to fall from carrier Strap screw missing (4.13 (a) (i))

Fail Offside Front Steering arm deformed (2.1.3 (c) (i))

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #4 2022-05-28 08:26

MOT test number 902800666412

Result X Failed

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #3 2021-05-25 09:36

MOT test number 304518535169

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2020-06-09 13:33

**MOT test number** 625960952736

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 4/12



MOT #1 2020-01-31 11:41

**MOT test number** 940700072768

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	7 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

MA66LGJ

report date: 2024-03-29

Owner history		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>		e?
*********		
***************************************		
************		
**********		
***************************************		
THE STREET STREET		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		

More info >

EXPERSE

CarCheck.co.uk page 9/12



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-02-16
Last registration	2023-11-04
Complete history	See info



Registration #1	2017-02-16	22 mi
Registration #2	2020-01-31	21.772 mi
Registration #3	2020-06-09	24.290 mi
Registration #4	2021-05-25	31.233 mi
Registration #5		11.777 es
Registration #6		11.177 es
Registration #7		11.777 es
Registration #8		11.177 es
Registration #9		11.177 mi
Registration #10		11.777 es
Registration #11		9.777 no

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



# Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1270 kg
Max. allowed weight	1695 kg

## Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles2Engine number2245020