





report date: 2024-03-28

General information

Make	MINI
Model	COUNTRYMAN COOPER D AUTO COOPER D
Colour	Silver
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-15

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



YH61WKK report date: 2024-03-28

MOT history

MOT expiry date	2024-08-19
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	18
Total items failed	7

MOT #14	2023-08-15 13:50
MOT test number	409089596044
Result	✓ Passed
Next expiry date	2024-08-19
Advice Items removed from driver's view prior to test	
Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both mounting bushes (5.3.4 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge (5.2.3	(e))

MOT #13		2022-08-17 09:28
MOT test	number	213190793201
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))	
Advice	Items removed from driver's view prior to test	
Advice	Offside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2022-08-17 08:29 450370783775 **MOT** test number Result × Failed Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) Pass with rectification Nearside Headlamp aim too low (4.1.2 (a)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e)) Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i)) **Advice** Items removed from driver's view prior to test Pass with rectification Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e)) **Advice**

MOT #11	2021-08-10 10:50
MOT test number	111903657610
Result	✓ Passed
MOT #10	2020-07-22 13:25
MOT test number	313910271605
Result	✓ Passed

MOT #9	9	2020-07-22 09:01
MOT te	st number	773361176894
Result		× Failed
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #8	2019-08-20 14:04
MOT test number	959421234757
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7		2018-11-27 17:01
MOT test	number	239352532220
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6		2018-11-27 15:25
MOT test	number	792078907917
Result		🗙 Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail E	xhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	

MOT #5	2017-11-30 15:51
MOT test number	200550938037
Result	✓ Passed
MOT #4	2016-10-11 14:47
MOT test number	910541415978
Result	✓ Passed
MOT #3	2016-10-10 12:52
MOT test number	142274836270
Result	× Failed
Fail Nearside Front Outer Tyre has ply or cords exposed (4.1.D.1b)	
Advice Offside front tyre low on tread on outer edge	

CarCheck.co.uk page 5/13



YH61WKK report date: 2024-03-28

MOT #2 2015-10-22 12:03

MOT test number 412397931610

Result ✓ Passed

Advice Front brake discs worn

Advice Rear brake pads getting low

Advice Nearside Front inner wheel rim slightly bent

MOT #1 2014-10-16 11:01

MOT test number 135499284201

Result ✓ Passed

CarCheck.co.uk page 6/13



YH61WKK report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	19 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
THE PARTY OF THE P	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NIE
Finds since	
Current registration	NE UK
Plada since	
	More info >
	11010 11110 /

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-10-27
Last registration	2023-08-15
Complete history	See info



Registration #1	2011-10-27	27 mi
Registration #2	2014-10-16	33.902 mi
Registration #3	2015-10-22	43.687 mi
Registration #4	2016-10-10	49.215 mi
Registration #5	2016-10-11	49.215 mi
Registration #6	2017-11-30	54.571 mi
Registration #7	2018-11-27	59.766 mi
Registration #8	2018-11-27	59.778 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 12/13



YH61WKK report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1335 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	47	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	e 13/13

Number of axles 2

Engine number 74337877