



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 S
Colour	Blue
Year of manufacture	2006
Top speed	140 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-09-19
Pictures	31
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-08
Pictures	31
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-01-20
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	20
Total items failed	21

MOT #20	2022-01-18 13:56
---------	------------------

MOT test number	518568801370
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-01-20
------------------	------------

- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Fail items only
- Advice** Oil leak, but not excessive turbo, 2ltrs of oil added to engine (8.4.1 (a) (i))
- Advice** Nearside Front headlamp lens slightly damaged
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #19** 2022-01-14 15:12**MOT test number** 571135601393**Result** ✗ Failed**Fail** Nearside Front Brake hose excessively deteriorated casing cracked (1.1.12 (b) (ii))**Advice** Nearside Front headlamp lens slightly damaged**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Oil leak, but not excessive turbo, 2ltrs of oil added to engine (8.4.1 (a) (i))**Fail** Offside Front Brake hose excessively deteriorated casing cracked (1.1.12 (b) (ii))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #18** 2021-01-21 15:12**MOT test number** 923028449601**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge All tyres (5.2.3 (e))**MOT #17** 2019-10-11 09:09**MOT test number** 957603129019**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))



MOT #16	2019-10-10 16:49
MOT test number	335132778021
Result	✗ Failed
Fail	Offside Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))
Fail	Electronic stability control warning lamp indicates a fault (7.12 (e))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))
Fail	Central Rear Seat belt not functioning as intended (7.1.2 (c))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #15**

2019-10-10 13:48

MOT test number

201877929328

Result**✗ Failed**

- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Central Rear Seat belt not functioning as intended (7.1.2 (c))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed webbing slightly (7.1.2 (b) (ii))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Seat belt webbing slightly damaged or frayed webbing slightly (7.1.2 (b) (ii))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #14

2018-08-20 15:07

MOT test number

625403207672

Result**✓ Passed****MOT #13**

2018-08-20 15:07

MOT test number

932751958931

Result**✗ Failed**

- Pass with rectification** Front Headlamp aim too low (4.1.2 (a))



MOT #12	2017-08-14 11:48
MOT test number	629146366098
Result	✓ Passed
MOT #11	2016-08-22 14:07
MOT test number	205569986325
Result	✓ Passed
MOT #10	2015-08-18 00:00
MOT test number	451971657256
Result	✓ Passed
MOT #9	2014-08-26 12:52
MOT test number	709908934296
Result	✓ Passed
MOT #8	2014-04-01 08:38
MOT test number	159011394434
Result	✓ Passed
MOT #7	2013-06-14 09:21
MOT test number	707575563139
Result	✓ Passed
MOT #6	2012-06-13 09:50
MOT test number	285595562173
Result	✓ Passed
MOT #5	2011-06-15 16:53
MOT test number	485096861186
Result	✓ Passed

**MOT #4** 2011-06-15 09:34**MOT test number** 218356561195**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #3** 2010-06-04 12:05**MOT test number** 714595550197**Result** ✓ Passed**MOT #2** 2010-05-25 14:57**MOT test number** 123805540198**Result** ✗ Failed**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #1** 2009-06-18 13:52**MOT test number** 430709569175**Result** ✓ Passed**Notice** Light scoring on front windscreen



Tax & MOT check

X

Untaxed

Tax expired:
1 December 2022

X

MOT

Expired:
20 January 2023

Tax status	Expired at 1 December 2022
Days left	516 days too late
MOT expiry date	20 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	FV06KCN
Plate since	2019-09-29
Current registration	FV06KCN
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-06-21
Last registration	2022-01-18
Complete history	See info



Registration #1	2006-06-21	22 mi
Registration #2	2009-06-18	65.367 mi
Registration #3	2010-05-25	85.968 mi
Registration #4	2010-06-04	86.504 mi
Registration #5	2011-06-15	92.578 mi
Registration #6	2011-06-15	92.578 mi
Registration #7	2012-06-13	96.092 mi
Registration #8	2013-06-14	100.932 mi
Registration #9	2014-04-01	104.851 mi
Registration #10	2014-08-26	105.327 mi
Registration #11	2015-08-18	112.122 mi
Registration #12	2016-08-22	118.105 mi
Registration #13	2016-08-22	118.105 mi
Registration #14	2016-08-22	118.105 mi
Registration #15	2016-08-22	118.105 mi
Registration #16	2016-08-22	118.105 mi
Registration #17	2016-08-22	118.105 mi
Registration #18	2016-08-22	118.105 mi
Registration #19	2016-08-22	118.105 mi
Registration #20	2016-08-22	118.105 mi
Registration #21	2016-08-22	118.105 mi
Registration #22	2016-08-22	118.105 mi
Registration #23	2016-08-22	118.105 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1804 mm
Height	1465 mm
Length	4710 mm
Wheel base	2755 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	304162