



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Grey
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-04-29
Pictures	8
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-30
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	31
Total items failed	5

MOT #14	2023-05-31 10:12
MOT test number	934048972721
Result	✓ Passed
Next expiry date	2024-05-30
Advice	Offside Rear Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))

MOT #13	2023-05-30 10:00
MOT test number	875745381325
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
DANGEROUS	Nearside Front Brake hose damaged and likely to fail insecure (1.1.12 (a))

MOT #12	2022-05-30 09:18
MOT test number	883675955325
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2020-09-22 15:57**MOT test number** 521036276675**Result** ✓ Passed

- Advice** Offside Rear Nail in tyre 215\70\16
- Advice** Wipers starting to smear
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing bad condition (5.2.3 (d) (ii))

**MOT #10** 2020-09-22 09:05**MOT test number** 298432439707**Result** ✗ Failed

- DANGEROUS** Fluid leaking continuously posing a serious risk to road safety water pipes corroded and leaking front to rear (8.4.1 (a) (ii))
- Advice** Offside Rear Nail in tyre 215\70\16
  - Advice** Wipers starting to smear
  - MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
  - Advice** Offside Rear Tyre slightly damaged/cracking or perishing bad condition (5.2.3 (d) (ii))

**MOT #9** 2019-09-25 10:39**MOT test number** 461842245675**Result** ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view zone B (3.2 (a) (i))

**MOT #8**

2018-09-26 09:46

**MOT test number**

515035308262

**Result**

✓ Passed

- Advice** Offside Front Valve stem slightly damaged (5.2.3 (j))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** N/s rear tyre 3mm 215/70/16c
- Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))
- Advice** Wear inner edge o/s front tyre 215/70/16c
- Advice** Corrosion underbody pipes

**MOT #7**

2017-09-13 13:32

**MOT test number**

357381227181

**Result**

✓ Passed

- Advice** Corrosion underbody pipes
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #6**

2016-09-15 09:25

**MOT test number**

856577340175

**Result**

✓ Passed

- Advice** Corrosion underbody pipes
- Advice** Offside Rear Tyre worn close to the legal limit 215/70/16c (4.1.E.1)
- Advice** Wipers starting to smear
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2016-09-15 09:25**MOT test number** 356482778752**Result** ✗ Failed**Advice** Corrosion underbody pipes**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Tyre worn close to the legal limit 215/70/16c (4.1.E.1)**Advice** Wipers starting to smear**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-09-18 09:34**MOT test number** 789606334477**Result** ✓ Passed**MOT #3** 2015-09-18 09:34**MOT test number** 250137456953**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2014-08-05 14:42**MOT test number** 326557514251**Result** ✓ Passed**Notice** Slight bind n/s rear brake (handbrake)



MOT #1	2014-08-05 12:00
MOT test number	506807014247
Result	✗ Failed
<div>Fail</div> Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)	
<div>Notice</div> Slight bind n/s rear brake (handbrake)	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
30 May 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	30 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-01
Last registration	2023-05-31
Complete history	<a href="#">See info</a>



Registration #1	2011-09-01	10 mi
Registration #2	2014-08-05	30.053 mi
Registration #3	2014-08-05	30.053 mi
Registration #4	2015-09-18	44.487 mi
Registration #5	2015-09-18	44.487 mi
Registration #6	2016-09-15	51.758 mi
Registration #7	2016-09-15	51.758 mi
Registration #8	2017-09-13	58.572 mi
Registration #9	2019-05-29	59.377 mi
Registration #10	2019-05-29	59.377 mi
Registration #11	2019-05-29	59.377 mi
Registration #12	2019-05-29	59.377 mi
Registration #13	2019-05-29	59.377 mi
Registration #14	2019-05-29	59.377 mi
Registration #15	2019-05-29	59.377 mi
Registration #16	2019-05-29	59.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

<b>Number of axles</b>	2
<b>Engine number</b>	D4CBB827791