



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	HI-ACE 280 GS SWB P/V (88BHP)
Colour	Silver
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	88 BHP
Max. torque	at 1.200 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Diesel





LABEL UNKNOWN



Internet history

Entry 1

Date	2022-06-19
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-08
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	16
Total items failed	14

MOT #19	2022-11-11 12:57
MOT test number	242626477507
Result	✓ Passed
Next expiry date	2023-11-10
Advice	Covers obscuring some components

MOT #18	2022-11-10 16:32
MOT test number	991375502054
Result	✗ Failed
Fail	Nearside Front Shock absorbers has an excessively worn bush (5.3.2 (c))
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
Advice	Covers obscuring some components
Fail	Offside Front Shock absorbers has an excessively worn bush (5.3.2 (c))

MOT #17	2021-12-10 14:52
MOT test number	608132980407
Result	✓ Passed
Minor	Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #16**

2020-12-07 16:46

MOT test number

938029943528

Result

✓ Passed

Advice

Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #15

2020-12-07 12:05

MOT test number

520860964059

Result

✗ Failed

Advice

Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

Advice

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail

Nearside Windscreen washer provides insufficient washer liquid n/s washer jet not working (3.5 (a))

Fail

Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

Fail

Nearside Front Service brake grabbing severely (1.2.1 (c))

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail

Rear fog lamp not working (4.5.1 (a) (ii))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #14

2019-12-09 10:27

MOT test number

667510130351

Result

✓ Passed

Advice

Offside Front washer jet weak

**MOT #13** 2018-12-14 14:12**MOT test number** 748994346828**Result** ✓ Passed**Advice** Engine cover fitted obscuring some testable components.**MOT #12** 2018-04-24 11:03**MOT test number** 812962642949**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit worn on outer edge (4.1.E.1)**MOT #11** 2017-04-25 11:53**MOT test number** 701308796461**Result** ✓ Passed**MOT #10** 2016-03-16 11:34**MOT test number** 863148172574**Result** ✓ Passed**Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #9** 2015-04-10 14:54**MOT test number** 845730505179**Result** ✓ Passed**MOT #8** 2014-04-01 11:45**MOT test number** 176471494045**Result** ✓ Passed**Notice** Surface corrosion to exhaust

**MOT #7** 2013-03-22 10:39**MOT test number** 427461483016**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-03-30 09:55**MOT test number** 135590492495**Result** ✓ Passed**MOT #5** 2012-03-30 09:55**MOT test number** 829950492077**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2011-04-04 10:10**MOT test number** 295964391097**Result** ✓ Passed**MOT #3** 2010-03-25 10:13**MOT test number** 674424380068**Result** ✓ Passed**MOT #2** 2009-03-12 11:19**MOT test number** 700091179046**Result** ✓ Passed



MOT #1	2009-03-12 09:12
MOT test number	253631479086
Result	✗ Failed
Fail	Offside Headlamp aim too high (1.8)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

X

Untaxed

Tax expired:
1 January 2024

✓

MOT

Expires:
8 April 2025

Tax status	Expired at 1 January 2024
Days left	120 days too late
MOT expiry date	8 April 2025
Full MOT history	See MOT history



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-04-12
Last registration	2022-11-11
Complete history	See info



Registration #1	2006-04-12	13 mi
Registration #2	2009-03-12	18.669 mi
Registration #3	2009-03-12	18.669 mi
Registration #4	2010-03-25	26.165 mi
Registration #5	2011-04-04	32.364 mi
Registration #6	2012-03-30	39.716 mi
Registration #7	2013-03-22	46.063 mi
Registration #8	2014-04-01	52.114 mi
Registration #9	2015-04-10	57.759 mi
Registration #10	2016-03-16	62.595 mi
Registration #11	2016-03-16	62.595 mi
Registration #12	2016-03-16	62.595 mi
Registration #13	2016-03-16	62.595 mi
Registration #14	2016-03-16	62.595 mi
Registration #15	2016-03-16	62.595 mi
Registration #16	2016-03-16	62.595 mi
Registration #17	2016-03-16	62.595 mi
Registration #18	2016-03-16	62.595 mi
Registration #19	2016-03-16	62.595 mi
Registration #20	2016-03-16	62.595 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Number of axles	2
Engine number	2KD1469797