



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T3
Colour	Blue
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 2

Date	2021-12-21
Pictures	8
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-12-13
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2022-12-19
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	17
Total items failed	12

MOT #19	2021-12-20 15:48
MOT test number	864480726885
Result	✓ Passed
Next expiry date	2022-12-19

MOT #18	2021-12-09 14:22
MOT test number	665586628767
Result	✗ Failed
MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	

MOT #17	2021-12-07 13:31
MOT test number	353411256408
Result	✗ Failed
MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
MAJOR Nearside Headlamp aim too high (4.1.2 (a))	

MOT #16	2020-12-07 15:15
MOT test number	427291537862
Result	✓ Passed

**MOT #15** 2020-12-07 15:15**MOT test number** 964141061781**Result** ✗ Failed**Pass with rectification**

Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #14 2020-02-28 10:03**MOT test number** 235182297207**Result** ✓ Passed**MOT #13** 2020-02-28 10:03**MOT test number** 909195273427**Result** ✗ Failed**Pass with rectification**Registration plate lamp inoperative in the case of a single lamp or all lamps
(4.7.1 (b) (ii))**MOT #12** 2019-03-01 12:33**MOT test number** 998675107871**Result** ✓ Passed**MOT #11** 2018-04-10 15:38**MOT test number** 278908648246**Result** ✓ Passed

**MOT #10** 2018-03-12 10:33**MOT test number** 891679267944**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Headlamp aim too low (1.8)**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view Wing mirror loose (8.1.2a)**MOT #9** 2017-03-20 14:52**MOT test number** 682278327371**Result** ✓ Passed**MOT #8** 2015-10-22 11:18**MOT test number** 309527371775**Result** ✓ Passed**Advice** Nsr tyre perrished**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2015-10-17 15:36**MOT test number** 872720084624**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nsr tyre perrished



MOT #6	2014-11-01 12:04
MOT test number	448865104383
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5	2014-10-25 15:11
MOT test number	486488894225
Result	✗ Failed
Fail	Nearside Front Windscreen wiper blade insecure (8.2.2)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #4	2013-11-14 17:45
MOT test number	509948413302
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #3	2012-11-14 13:27
MOT test number	387069412390
Result	✓ Passed



MOT #2	2011-11-12 09:52
MOT test number	588956211300
Result	✓ Passed
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #1	2010-10-25 12:36
MOT test number	723648190211
Result	✓ Passed
Notice	Nearside rear tyre outer wall damaged
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-11-16
Last registration	2021-12-20
Complete history	See info



Registration #1	2007-11-16	12 mi
Registration #2	2010-10-25	27.941 mi
Registration #3	2011-11-12	41.018 mi
Registration #4	2012-11-14	55.022 mi
Registration #5	2013-11-14	66.236 mi
Registration #6	2014-10-25	72.738 mi
Registration #7	2014-11-01	73.142 mi
Registration #8	2015-10-17	78.225 mi
Registration #9	2015-10-22	78.579 mi
Registration #10	2017-03-20	86.581 mi
Registration #11	2018-03-12	99.241 mi
Registration #12	2019-03-20	111.217 mi
Registration #13	2019-03-20	111.217 mi
Registration #14	2019-03-20	111.217 mi
Registration #15	2019-03-20	111.217 mi
Registration #16	2019-03-20	111.217 mi
Registration #17	2019-03-20	111.217 mi
Registration #18	2019-03-20	111.217 mi
Registration #19	2019-03-20	111.217 mi
Registration #20	2019-03-20	111.217 mi
Registration #21	2019-03-20	111.217 mi
Registration #22	2019-03-20	111.217 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	2AD521824