



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 2

Date	2022-01-11
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2022-01-11
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-02-19
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	51
Total items failed	29

MOT #23	2023-02-20 09:52
MOT test number	758371595116
Result	✓ Passed
Next expiry date	2024-02-19
Advice	Heavily undersealed

MOT #22	2023-02-17 14:19
MOT test number	729125183026
Result	✗ Failed
MAJOR	Exhaust has a major leak of exhaust gases (6.1.2 (a))
Advice	Heavily undersealed
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #21	2022-02-18 15:16
MOT test number	918871705518
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Under car covered in under seal
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #20**

2022-02-18 15:16

MOT test number

928174075452

Result

✗ Failed

Pass with rectification Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Under car covered in under seal**Pass with rectification** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**MOT #19**

2021-02-19 17:19

MOT test number

230333548597

Result

✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #18**

2021-02-19 09:58

MOT test number

767005104606

Result

✗ Failed

MAJOR Nearside Front Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Central Front Exhaust silencer insecure (8.1.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

**MOT #17**

2019-05-04 09:44

MOT test number

286694736607

Result

✓ Passed

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2019-05-04 08:52

MOT test number

404026813631

Result

✗ Failed

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Offside Headlamp aim too high (4.1.2 (a))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR

Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

MOT #15

2018-05-08 16:13

MOT test number

528475241868

Result

✓ Passed

Advice

Exhaust centre box mounting corroded and broken

Advice

Brake pipe slightly corroded front to rear (3.6.B.2c)

**MOT #14**

2018-05-08 11:22

MOT test number

237372030078

Result

✗ Failed

- Fail** Rear registration plate deteriorated (6.3.1d)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Exhaust centre box mounting corroded and broken
- Advice** Brake pipe slightly corroded front to rear (3.6.B.2c)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Brake pipe excessively corroded front to rear (3.6.B.2c)

MOT #13

2017-05-06 07:58

MOT test number

903127076696

Result

✓ Passed

- Advice** Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #12

2017-05-05 14:17

MOT test number

705359144051

Result

✗ Failed

- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Advice** Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #11

2016-05-09 16:42

MOT test number

675509560038

Result

✓ Passed

**MOT #10**

2016-05-09 11:57

MOT test number

733521619043

Result**✗ Failed**

- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Main beam 'tell-tale' not working (1.7.4c)
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Hazard warning tell tale not working correctly (1.4.B.1e)
- Fail** Nearside Upper Rear position lamp(s) not working (1.1.A.3b)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Indicator tell tale inoperative (1.4.A.2a)
- Fail** Front Tyre tread depth below requirements of 1.6mm both (4.1.E.1)
- Fail** Hazard warning switch faulty (1.4.B.1d)
- Fail** Rear fog lamp tell tale not working (1.3.1b)
- Fail** Offside Stop lamp not working (1.2.1b)

MOT #9

2015-05-11 13:16

MOT test number

346241935139

Result**✓ Passed**

- Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2015-05-09 12:00**MOT test number** 539349325133**Result** ✗ Failed

- Fail** Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2014-05-12 12:18**MOT test number** 529192834160**Result** ✓ Passed**MOT #6** 2014-05-10 11:52**MOT test number** 317670534154**Result** ✗ Failed

- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #5 2013-05-09 14:59**MOT test number** 858299423103**Result** ✓ Passed

- Notice** Nearside rear tyre has a cut in tread
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2013-05-09 12:25**MOT test number** 215729323132**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nearside rear tyre has a cut in tread**Fail** Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front coil spring incomplete (2.4.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2012-05-10 14:52**MOT test number** 219501532163**Result** ✓ Passed**Advice** Nearside Front front brake juddering slightly (3.7.A.2b)**Notice** Bearing and or tyre noise on the road**Advice** Offside Front front brake juddering slightly (3.7.A.2b)**Notice** Osr bumper damaged**MOT #2** 2011-05-03 17:39**MOT test number** 486583421128**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear discs showing signs of wear



MOT #1	2010-05-11 12:42
MOT test number	224551430196
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
30 September 2023

✕
MOT

Expired:
19 February 2024

Tax status	Expired at 30 September
Days left	212 days too late
MOT expiry date	19 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 TF07JNV
Plate since	2019-09-29
Current registration	 TF07JNV
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-07-11
Last registration	2023-02-20
Complete history	See info



Registration #1	2007-07-11	23 mi
Registration #2	2010-05-11	23.771 mi
Registration #3	2011-05-03	29.430 mi
Registration #4	2012-05-10	35.246 mi
Registration #5	2013-05-09	41.476 mi
Registration #6	2013-05-09	41.476 mi
Registration #7	2014-05-10	43.042 mi
Registration #8	2014-05-12	43.042 mi
Registration #9	2015-05-09	51.732 mi
Registration #10	2015-05-11	51.742 mi
Registration #11	2016-05-09	57.742 mi
Registration #12	2017-05-05	63.663 mi
Registration #13	2017-05-06	63.663 mi
Registration #14	2018-05-09	63.663 mi
Registration #15	2018-05-09	63.663 mi
Registration #16	2018-05-09	63.663 mi
Registration #17	2018-05-09	63.663 mi
Registration #18	2018-05-09	63.663 mi
Registration #19	2018-05-09	63.663 mi
Registration #20	2018-05-09	63.663 mi
Registration #21	2018-05-09	63.663 mi
Registration #22	2018-05-09	63.663 mi
Registration #23	2018-05-09	63.663 mi
Registration #24	2018-05-09	63.663 mi
Registration #25	2018-05-09	63.663 mi



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118