



report date: 2024-03-29

General information

Make	CITROEN
Model	C8 16V SX
Colour	Blue
Year of manufacture	2006
Top speed	117 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	195 Nm at 4.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.5 mpg
Consumption extra urban	38.7 mpg
Consumption combined	31.4 mpg
CO2 emission	213 g/km
CO2 label	K



**MOT history**

MOT expiry date	2022-02-27
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	55
Total items failed	4

MOT #17 2021-02-24 14:16**MOT test number** 196300365986**Result** Passed**Next expiry date** 2022-02-27

- Advice** Offside Rear light cracked
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Outer Tyre worn close to legal limit/worn on edge ns/os (5.2.3 (e))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))

MOT #16 2020-02-17 10:32**MOT test number** 489045997863**Result** Passed

- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #15**

2019-02-26 08:58

MOT test number

316550548339

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Front Exhaust has a minor leak of exhaust gases gas leak from front flexi (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2019-02-25 13:35

MOT test number

262010233735

Result

✗ Failed

- DANGEROUS** Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Advice** Central Front Exhaust has a minor leak of exhaust gases gas leak from front flexi (6.1.2 (a))
 - Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
 - Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- DANGEROUS** Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
 - Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13**

2018-02-28 11:08

MOT test number

939325074633

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Exhaust silencer getting corroded
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Exhaust has a minor leak of exhaust gases front flexi (7.1.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12

2018-02-15 12:45

MOT test number

223156964961

Result

✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Fail** Nearside Front Suspension arm has excessive play in a ball joint bottom ball joint (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Exhaust silencer getting corroded
- Advice** Exhaust has a minor leak of exhaust gases front flexi (7.1.2)

**MOT #11**

2017-02-18 09:02

MOT test number

619518206826

Result

✓ Passed

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice

Rear Panhard rod rubber bush deteriorated but not resulting in excessive movement n/s and o/s (2.4.G.2)

Advice

Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #10

2016-02-09 10:01

MOT test number

131064115325

Result

✓ Passed

Advice

Advise: n/s/r sill damaged

Advice

Nearside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice

Advise: rear child seats fitted

MOT #9

2015-02-18 09:51

MOT test number

119199245029

Result

✓ Passed

Notice

Child seat fitted not allowing full inspection of adult belt

Notice

Nail in offside rear tyre

Notice

Advise: slight damage to n/s/r of sill

MOT #8

2014-01-24 11:26

MOT test number

765694124044

Result

✓ Passed



MOT #7	2013-02-14 13:08
MOT test number	139705043444
Result	✓ Passed
Notice	Advise: slight damage to n/s sill
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #6	2012-02-04 16:07
MOT test number	126005632052
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	N/s/r and o/s/r rear most seat child seats fitted
Notice	Dent in n/s/r outer sill
Notice	Vehicle's internal headlight adjuster altered to recheck lights

MOT #5	2012-02-04 13:03
MOT test number	628815832052
Result	✗ Failed
Fail	Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Notice	Vehicle's internal headlight adjuster altered to recheck lights
Notice	Child seat fitted not allowing full inspection of adult belt
Fail	Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Notice	N/s/r and o/s/r rear most seat child seats fitted
Notice	Dent in n/s/r outer sill

**MOT #4** 2011-01-25 12:44**MOT test number** 499685021060**Result** ✓ Passed**Advice** Centre Front Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Centre Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2010-02-12 13:01**MOT test number** 133653540488**Result** ✓ Passed**MOT #2** 2010-02-09 11:02**MOT test number** 303590640039**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Exhaust has part of the system excessively deteriorated (7.1.1a)**Notice** Nail in offside rear tyre**MOT #1** 2009-02-20 11:35**MOT test number** 520821859091**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
28 February 2022

✕
MOT

Expired:
27 February 2022

Tax status	Expired at 28 February 2022
Days left	791 days too late
MOT expiry date	27 February 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-06-29
Current registration	 XXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-22
Last registration	2021-02-24
Complete history	See info



Registration #1	2006-03-22	9 mi
Registration #2	2009-02-20	26.947 mi
Registration #3	2010-02-09	34.186 mi
Registration #4	2010-02-12	34.214 mi
Registration #5	2011-01-25	38.880 mi
Registration #6	2012-02-04	44.520 mi
Registration #7	2012-02-04	44.520 mi
Registration #8	2013-02-14	49.483 mi
Registration #9	2014-01-24	53.407 mi
Registration #10	2015-01-20	55.377 mi
Registration #11	2015-01-20	55.377 mi
Registration #12	2015-01-20	55.377 mi
Registration #13	2015-01-20	55.377 mi
Registration #14	2015-01-20	55.377 mi
Registration #15	2015-01-20	55.377 mi
Registration #16	2015-01-20	55.377 mi
Registration #17	2015-01-20	55.377 mi
Registration #18	2015-01-20	55.377 mi

More info >



Dimensions & weight

Width	2194 mm
Height	1752 mm
Length	4726 mm
Wheel base	2823 mm
Kerb weight	1612 kg
Max. allowed weight	2405 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	LH4M1438518