





report date: 2024-03-29

# General information

Make	FORD
Model	KA ZETEC
Colour	White
Year of manufacture	2017
Top speed	99 mph
0 - 100 km/h	15.3 seconds
0 - 60 mph	15.3 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	51.5 kW / 70 HP / 69 BHP
Max. torque	105 Nm at 4.000 rpm
Engine capacity	1.198 сс
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	70.6 mpg
Consumption combined	56.5 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29


# Internet history

#### Entry 3

Date 2021-07-03

Pictures 36

Listing price <u>View report</u>









source: heycar.co.uk

Entry 2

Date 2021-06-24

Pictures 35

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-06-23

Pictures 36

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



**MOT** history

MOT expiry date	2024-05-15
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #6		2023-05-16 14:31
MOT test	number	823533793115
Result		<b>✓</b> Passed
Next exp	ry date	2024-05-15
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (	5.2.3 (e))
Minor (i))	Offside Front Drive shaft joint constant velocity boot severely deteriorate	ed leaking grease (6.1.7 (g)
Advice	Offside Front fog lamp not working, lamp damaged	
Minor	Offside Windscreen damaged but not adversely affecting driver's view of	hip in screen (3.2 (a) (i))
Advice	Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1	1 (a) (ii))

CarCheck.co.uk page 3/12



MOT #2

Result

WR67LFA

report date: 2024-03-29

× Failed

**MOT #5** 2023-05-16 14:31 713640151514 **MOT** test number Result × Failed **Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) **Minor** Offside Windscreen damaged but not adversely affecting driver's view chip in screen (3.2 (a) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) Pass with rectification Offside Headlamp aim too low (4.1.2 (a)) **Advice** Offside Front fog lamp not working, lamp damaged **Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated leaking grease (6.1.7 (g) (i))

MOT #4	2022-06-09 09:48
MOT test number	230738174128
Result	✓ Passed

MO1 #3	2021-00-21 11.41
MOT test number	735275895018

MOT #2 2021-06-18 16:09

**MOT test number** 642145396820

MAJOR Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2020-10-19 16:25

**MOT test number** 604532170428

**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn edges and 3 - 4 mm (5.2.3 (e))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge inner shoulder worn and 3 - 4 mm

remainder (5.2.3 (e))

CarCheck.co.uk page 5/12



report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 May 2024
Full MOT history	See MOT history

# Tax calculation

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

WR67LFA

report date: 2024-03-29

# For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a>. More info >

# Plate changes

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-10-24
Last registration	2023-05-16
Complete history	See info



Registration #1	2017-10-24	10 mi
Registration #2	2020-10-19	16.918 mi
Registration #3	2021-06-18	20.690 mi
Registration #4	2021-06-21	20.690 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		T1.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1911 mm
Height	1521 mm
Length	3929 mm
Wheel base	2489 mm
Kerb weight	955 kg
Max. allowed weight	1500 kg

# Additional information

Fuel tank capacity	42	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of axles CarCheck.co.uk	2	page 12/12