





report date: 2024-03-28

General information

Make	MAZDA
Model	cx-3 D SE-L NAV
Colour	White
Year of manufacture	2018
Top speed	110 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	270 Nm at 1.600 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-02-17

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-02-20
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	10
Total items failed	5

MOT #5	2024-02-21 13:44
MOT test number	442736224622
Result	✓ Passed
Next expiry date	2025-02-20
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2024-01-23 12:59
MOT test number	190381574062
Result	X Failed
Fail Electronic stability control warning lamp indicates a fault (7.12 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps of (b) (i))	r light sources (4.7.1
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to re (5.2.3 (d) (i))	each the ply or cords
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.	3 (h))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

CarCheck.co.uk page 3/11



MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2022-01-24 22:05
MOT test number	327640124779
Result	✓ Passed
Advice Protective shields fitted underneath vehicle	

MOT #1	2021-06-26 09:07
MOT test number	740135704740
Result	✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	20 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	AIR SIE
Plate since	
Current registration	NIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-07-05
Last registration	2024-02-21
Complete history	See info



Registration #1	2018-07-05	6 mi
Registration #2	2021-06-26	35.361 mi
Registration #3	2022-01-24	43.711 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		0.00 44
Registration #7		91,777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	85%
Children	79%
Pedestrian	84%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1535 mm
Length	4275 mm
Wheel base	2570 mm
Kerb weight	1200 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	S5 30 410382

CarCheck.co.uk page 11/11