



GJ6IEFZ

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	Blue
Year of manufacture	-
Top speed	93 mph
0 - 60 mph	16.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	225 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN

**MOT history**

MOT #14	2020-10-14 10:26
MOT test number	219484393751
Result	✓ Passed
Next expiry date	2021-10-13

MOT #13	2020-10-13 14:07
MOT test number	412338392539
Result	✗ Failed
Fail Bonnet primary retaining device ineffective (3.1 (c))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	

MOT #12	2019-10-02 13:37
MOT test number	473154467720
Result	✓ Passed

MOT #11	2019-10-02 07:56
MOT test number	359393690326
Result	✗ Failed
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail Tyre tread depth below requirements of 1.6mm both rear (5.2.3 (e))	
Fail Rear Seat belt not functioning as intended center belt (7.1.2 (c))	

MOT #10	2018-10-04 10:53
MOT test number	379970082283
Result	✓ Passed



MOT #9	2018-10-01 10:12
MOT test number	138543360670
Result	✗ Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8	2017-09-19 10:42
MOT test number	134871157315
Result	✓ Passed

**MOT #7**

2017-09-18 12:12

MOT test number

607140105761

Result**✗ Failed****Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake fluctuating, but not excessively both (3.7.B.3)**Advice** Offside Rear Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Spare tyre defective**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Fuel pipe leaking (7.2.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)**Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6**

2016-09-29 14:27

MOT test number

391192227491

Result**✓ Passed**

**MOT #5** 2016-09-29 13:04**MOT test number** 977802191749**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2015-09-29 14:23**MOT test number** 158286635347**Result** ✓ Passed**Advice** OSR tyre has cuts and worn on inner edge, Oil leak**MOT #3** 2015-09-29 10:54**MOT test number** 151463209740**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** OSR tyre has cuts and worn on inner edge, Oil leak**MOT #2** 2014-09-28 13:39**MOT test number** 868331674204**Result** ✓ Passed

**MOT #1**

2014-09-27 09:54

MOT test number

149150274258

Result**✗ Failed****Fail**

Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail

Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Fail

Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail

Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail

Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail

Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-28
Last registration	2020-10-14
Complete history	See info



Registration #1	2011-09-28	16 mi
Registration #2	2014-09-27	101.677 mi
Registration #3	2014-09-28	101.677 mi
Registration #4	2015-09-29	117.931 mi
Registration #5	2015-09-29	117.931 mi
Registration #6	2016-09-29	132.115 mi
Registration #7	2016-09-29	132.115 mi
Registration #8	2017-09-18	154.845 mi
Registration #9	2018-09-28	168.577 mi
Registration #10	2019-09-28	182.309 mi
Registration #11	2020-09-28	196.041 mi
Registration #12	2021-09-28	209.773 mi
Registration #13	2022-09-28	223.505 mi
Registration #14	2023-09-28	237.237 mi
Registration #15	2024-09-28	250.969 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Kerb weight	1475 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	CAY C55081