



report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI XS
Colour	Blue
Year of manufacture	2006
Top speed	113 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.8 mpg
CO2 emission	204 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-11
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-19
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #18	2023-09-14 11:00
MOT test number	304089294748
Result	✓ Passed
Next expiry date	2024-09-19
Advice	Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Underside corroded
Advice	Power steering component has slight seepage from a component (2.1.5 (a))

MOT #17	2022-09-15 16:26
MOT test number	472408795138
Result	✓ Passed

**MOT #16**

2021-09-20 09:44

MOT test number

944614903228

Result

✓ Passed

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Drive belt cracked
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Parking brake pivot on rear axle sticking
- Advice** Spare tyre defective
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake pipe corroded, covered in grease or other material both main (1.1.11 (c))

MOT #15

2021-01-18 14:59

MOT test number

743320693175

Result

✓ Passed

MOT #14

2020-01-22 17:21

MOT test number

430402912753

Result

✓ Passed

MOT #13

2020-01-22 10:15

MOT test number

897855984917

Result

✗ Failed

- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #12** 2019-06-11 11:36**MOT test number** 663677571596**Result** ✓ Passed**Advice** Nearside Front Body mounting fixing insecure, but overall security not significantly reduced (6.2.2 (c) (i))**Advice** Nearside Power steering component has slight seepage from a component steering rack (2.1.5 (a))**Minor** Offside Front Power steering fluid level below minimum (2.1.5 (b) (i))**Advice** Plastic cover sills fitted**MOT #11** 2018-06-05 10:42**MOT test number** 959215620797**Result** ✓ Passed**Advice** Nearside Power steering component has slight seepage from a component rack (2.1.5 (a))**MOT #10** 2018-06-05 10:42**MOT test number** 723085026948**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Offside Position lamp not working (4.2.1 (a))**Advice** Nearside Power steering component has slight seepage from a component rack (2.1.5 (a))**MOT #9** 2017-06-05 10:29**MOT test number** 614691565807**Result** ✓ Passed**MOT #8** 2016-06-03 09:55**MOT test number** 568318400762**Result** ✓ Passed

**MOT #7** 2015-06-03 09:26**MOT test number** 345234755172**Result** ✓ Passed**MOT #6** 2014-06-03 09:30**MOT test number** 106394354115**Result** ✓ Passed**MOT #5** 2013-06-03 09:21**MOT test number** 298234553177**Result** ✓ Passed**MOT #4** 2012-06-06 10:57**MOT test number** 858968652188**Result** ✓ Passed**Notice** Rear Exhaust Rubber Mounting Split**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Misting of oil around Turbocharger Intercooler**MOT #3** 2011-06-30 10:45**MOT test number** 947961881160**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**MOT #2** 2010-06-24 12:22**MOT test number** 140155870197**Result** ✓ Passed



MOT #1	2009-07-03 09:18
MOT test number	684774689177
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	DA06WDZ
Plate since	2024-03-29
Current registration	DA06WDZ
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-06-29
Last registration	2023-09-14
Complete history	See info



Registration #1	2006-06-29	14 mi
Registration #2	2009-07-03	7.415 mi
Registration #3	2010-06-24	9.752 mi
Registration #4	2011-06-30	12.474 mi
Registration #5	2012-06-06	14.679 mi
Registration #6	2013-06-03	17.263 mi
Registration #7	2014-06-03	22.471 mi
Registration #8	2015-06-03	28.249 mi
Registration #9	2016-06-03	33.177 mi
Registration #10	2017-06-05	38.772 mi
Registration #11	2018-06-05	44.367 mi
Registration #12	2019-06-05	49.962 mi
Registration #13	2020-06-05	55.557 mi
Registration #14	2021-06-05	61.152 mi
Registration #15	2022-06-05	66.747 mi
Registration #16	2023-06-05	72.342 mi
Registration #17	2024-06-05	77.937 mi
Registration #18	2025-06-05	83.532 mi
Registration #19	2026-06-05	89.127 mi
Registration #20	2027-06-05	94.722 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Kerb weight	2065 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4CB5937723