



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT 200 LIMITED TDCI
Colour	Grey
Year of manufacture	2019
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.499 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	2.8 mpg
CO2 emission	115 g/km
CO2 label	C





## Internet history

### Entry 3

Date 2022-02-22

Pictures 9

Listing price [View report](#)





source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2

Date 2021-08-22

Pictures 19

Listing price [View report](#)



source: [yesauto.com](https://www.yesauto.com)

### Entry 1

Date 2021-07-08

Pictures 9

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-03-10
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	14
Total items failed	4

MOT #6	2023-02-21 10:27
MOT test number	526281791078
Result	✓ Passed
Next expiry date	2024-03-10
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Covers and shields restricts view
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords area of tread (5.2.3 (d) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #5**

2023-02-21 10:27

**MOT test number**

747697945590

**Result****✗ Failed****Pass with rectification**

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice**

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords area of tread (5.2.3 (d) (i))

**Advice**

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Pass with rectification**

Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Covers and shields restricts view

**MOT #4**

2022-03-09 10:04

**MOT test number**

636448737046

**Result****✓ Passed****Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #3**

2022-03-08 14:29

**MOT test number**

630238991353

**Result****✗ Failed****Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail**

Offside Front Brake pipe excessively damaged (1.1.11 (c))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #2**

2021-03-11 11:01

**MOT test number**

904996959570

**Result****✓ Passed**



MOT #1	2021-03-10 15:20
MOT test number	164801959201
Result	✗ Failed
Fail	Central Seat belt buckle not functioning as intended (7.1.2 (d))



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 September 2024

✗  
**MOT**  
  
Expired:  
10 March 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	10 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2019-02-21
Last registration	2023-02-21
Complete history	<a href="#">See info</a>



Registration #1	2019-02-21	11 mi
Registration #2	2021-03-10	9.720 mi
Registration #3	2021-03-11	9.720 mi
Registration #4	2023-02-21	9.720 mi
Registration #5	2023-02-21	9.720 mi
Registration #6	2023-02-21	9.720 mi
Registration #7	2023-02-21	9.720 mi
Registration #8	2023-02-21	9.720 mi
Registration #9	2023-02-21	9.720 mi
Registration #10	2023-02-21	9.720 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	92%
Children	79%
Pedestrian	65%
Safety systems	75%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1835 mm
Height	1844 mm
Length	4425 mm
Kerb weight	1527 kg
Max. allowed weight	2245 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	KC03126