



report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 16V
Colour	Black
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	256 BHP
Max. torque	380 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	34.9 mpg
Consumption combined	27.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-28
Pictures	32
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #18	2021-03-12 16:28
MOT test number	664971370270
Result	✓ Passed
Next expiry date	2022-03-13

MOT #17	2020-03-13 17:56
MOT test number	756989766618
Result	✓ Passed

MOT #16	2020-03-10 15:01
MOT test number	388869787424
Result	✗ Failed

- Fail** Road wheel fixing missing one from each wheel (5.2.1 (a) (i))
- Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #15	2019-03-05 15:55
MOT test number	539825575241
Result	✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #14**

2019-03-05 13:13

MOT test number

922572056169

Result**✗ Failed****Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13**

2018-02-22 13:30

MOT test number

390238116313

Result**✓ Passed****MOT #12**

2018-02-21 11:51

MOT test number

222680026431

Result**✗ Failed****Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #11**

2017-03-11 08:54

MOT test number

243451255755

Result**✓ Passed**

**MOT #10** 2017-03-11 08:54**MOT test number** 864122857212**Result** ✗ Failed**Pass with rectification** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Pass with rectification** Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #9** 2016-03-11 10:18**MOT test number** 631132558866**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8** 2016-03-11 10:18**MOT test number** 483404823200**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Nearside Front Anti-roll bar linkage damaged and seriously weakened (2.4.G.1)**MOT #7** 2015-03-12 09:34**MOT test number** 166551775065**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #6** 2015-03-12 09:34**MOT test number** 688771275005**Result** ✗ Failed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2014-03-12 13:43**MOT test number** 175631674426**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-02-20 09:27**MOT test number** 595281453044**Result** ✓ Passed**MOT #3** 2013-02-19 17:22**MOT test number** 947950053024**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage fractured (2.4.G.1)



MOT #2	2012-03-14 11:23
MOT test number	185554772031
Result	✓ Passed
Notice	Front brake discs pitted and corroded on the inner faces
Notice	Under-trays fitted obscuring some underside components
Notice	Oil leak rear differential
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2011-03-25 12:11
MOT test number	506594181096
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-22
Last registration	2021-03-12
Complete history	See info



Registration #1	2008-04-22	10 mi
Registration #2	2011-03-25	43.240 mi
Registration #3	2012-03-14	54.654 mi
Registration #4	2013-02-19	67.263 mi
Registration #5	2013-02-20	67.263 mi
Registration #6	2014-03-12	75.942 mi
Registration #7	2015-03-12	83.777 mi
Registration #8	2016-03-11	89.629 mi
Registration #9	2016-03-11	89.629 mi
Registration #10	2017-03-11	94.565 mi
Registration #11	2018-03-11	94.565 mi
Registration #12	2018-03-11	94.565 mi
Registration #13	2018-03-11	94.565 mi
Registration #14	2018-03-11	94.565 mi
Registration #15	2018-03-11	94.565 mi
Registration #16	2018-03-11	94.565 mi
Registration #17	2018-03-11	94.565 mi
Registration #18	2018-03-11	94.565 mi
Registration #19	2018-03-11	94.565 mi

More info >



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4680 mm
Wheel base	2750 mm
Kerb weight	1695 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L3 20279163