



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SE
Colour	Silver
Year of manufacture	2004
Top speed	123 mph
0 - 60 mph	10.4 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	181 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	39.8 mpg
Consumption combined	31.0 mpg
CO2 emission	211 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-09-15
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-09-22
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	24
Total items failed	18

MOT #21 2021-09-23 16:31

MOT test number 912465140057

Result ✓ Passed

Next expiry date 2022-09-22

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #20 2021-09-18 13:15

MOT test number 658576908219

Result ✗ Failed

Fail Nearside Rear Parking (secondary brake) on a single line braking system grabbing severely (1.3.1 (c))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #19** 2020-09-16 11:32**MOT test number** 156199290190**Result** ✓ Passed**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Rear exhaust corroded**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #18** 2019-09-17 11:14**MOT test number** 225508636669**Result** ✓ Passed**Advice** Rear exhaust corroded**MOT #17** 2019-09-17 11:14**MOT test number** 940026820168**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear exhaust corroded

**MOT #16**

2018-09-11 11:54

MOT test number

879873349316

Result

✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Parking brake needs slight adjustment
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15

2017-09-08 11:13

MOT test number

596399679616

Result

✓ Passed

MOT #14

2017-09-08 08:32

MOT test number

989767427254

Result

✗ Failed

- Fail** Offside Headlamp aim too low (1.8)
- Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
- Fail** Power steering pipe(s) or hose(s) leaking from a joint (2.3.3b)

MOT #13

2016-09-16 14:11

MOT test number

523315356410

Result

✓ Passed

MOT #12

2016-09-16 08:27

MOT test number

376345768885

Result

✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #11** 2015-09-11 08:59**MOT test number** 884514233763**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Item(s) removed from drivers view**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2014-09-09 09:11**MOT test number** 229972554216**Result** ✓ Passed**MOT #9** 2013-09-05 15:59**MOT test number** 895038643219**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #8** 2013-09-05 14:59**MOT test number** 828648843294**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

**MOT #7** 2012-09-13 13:31**MOT test number** 237107952279**Result** ✓ Passed**MOT #6** 2012-09-12 09:45**MOT test number** 359826652468**Result** ✗ Failed

- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Offside Headlamp aim too low (1.8)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

MOT #5 2011-09-09 10:40**MOT test number** 457182451230**Result** ✓ Passed**MOT #4** 2010-09-10 09:25**MOT test number** 573173150222**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2009-09-14 09:28**MOT test number** 161567059262**Result** ✓ Passed



MOT #2	2008-09-15 09:28
MOT test number	654109958265
Result	✓ Passed
MOT #1	2007-09-04 16:14
MOT test number	644457847278
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 March 2022

✕
MOT

Expired:
22 September 2022

Tax status	Expired at 1 March 2022
Days left	790 days too late
MOT expiry date	22 September 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-09-16
Last registration	2021-09-23
Complete history	See info



Registration #1	2004-09-16	19 mi
Registration #2	2007-09-04	14.372 mi
Registration #3	2008-09-15	18.565 mi
Registration #4	2009-09-14	22.815 mi
Registration #5	2010-09-10	26.754 mi
Registration #6	2011-09-09	43.786 mi
Registration #7	2012-09-12	53.923 mi
Registration #8	2012-09-13	53.924 mi
Registration #9	2013-09-05	61.016 mi
Registration #10	2013-09-05	61.016 mi
Registration #11	2014-09-09	67.387 mi
Registration #12	2015-09-11	73.829 mi
Registration #13	2016-09-11	75.000 mi
Registration #14	2017-09-11	75.000 mi
Registration #15	2018-09-11	75.000 mi
Registration #16	2019-09-11	75.000 mi
Registration #17	2020-09-11	75.000 mi
Registration #18	2021-09-11	75.000 mi
Registration #19	2022-09-11	75.000 mi
Registration #20	2023-09-11	75.000 mi
Registration #21	2024-09-11	75.000 mi
Registration #22	2025-09-11	75.000 mi
Registration #23	2026-09-11	75.000 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1306 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	G4GC3781896