





report date: 2024-03-29

General information

Make	KIA
Model	RIO 16V
Colour	Black
Year of manufacture	2009
Top speed	110 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

MOT history

MOT expiry date	2021-09-13
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	30
Total items failed	2

MOT #10		2020-09-14 12:55
MOT test	number	155771499433
Result		✓ Passed
Next expi	y date	2021-09-13
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1	1.11 (c))
Advice	Offside Brake pipe corroded, covered in grease or other material front to	rear (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Non obligatory mirror damaged	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material	(1.1.11 (c))
Advice	Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))	
Advice	Front Exhaust mounting defective (6.1.2 (a))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/12



SD59OPZ

report date: 2024-03-29

MOT #9 2020-09-14 12:55 359919094364 **MOT** test number Result **X** Failed **Advice** Nearside Non obligatory mirror damaged Advice Front Exhaust mounting defective (6.1.2 (a)) Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice **Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c)) Pass with rectification Offside Track rod end ball joint has excessive play (2.1.3 (b) (i)) Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Pass with rectification Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #8	2019-06-28 12:00
MOT test number	994900273232
Result	✓ Passed
Advice Front Exhaust silencer slightly loose (8.1.1 (b) (i)) Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #7 MOT test number	2018-06-25 10:44 764919557272
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number
774430334753

Result
Advice Nearside Rear lamp cover damaged
Advice Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Brake pipe slightly corroded front to rear (3.6.B.2c)

MOT #5 2016-06-21 11:11 **MOT** test number 967947091840 Result Passed Advice Windscreen washers are partially blocked but provide adequate washer fluid Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2) Advice Nearside rear tail lamp is cracked **Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)

MOT #4	2015-06-29 16:14
MOT test number	419820985101
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2015-01-07 14:38
MOT test number	927927205085
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #2	2013-09-04 10:10
MOT test number	549487143285
Result	✓ Passed
MOT #1	2012-09-05 10:23
MOT test number	187139142240
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax expired: 30 December 2020

X MOT

Expired: 13 September 2021

Tax status	Expired at 30 December 2020
Days left	1216 days too late
MOT expiry date	13 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SD590PZ report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here .	

	More info >
	More into >
Plate changes	
See in this check if this KIA had different number plates.	
See in this eneck is this fairthad different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK
Plate since	200.00.00
	Mana infa
	More info >

CarCheck.co.uk page 9/12



SD59OPZ

report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-10-06
Last registration	2020-09-14
Complete history	See info



Registration #1	2009-10-06	9 mi
Registration #2	2012-09-05	27.796 mi
Registration #3	2013-09-04	34.887 mi
Registration #4	2015-01-07	45.873 mi
Registration #5	2015-06-29	48.683 mi
Registration #6	2016-06-21	57.610 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
60501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1154 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number G4EE9H252216