



report date: 2024-03-29

General information

Make	BMW
Model	525 325D M SPORT TOURING
Colour	Grey
Year of manufacture	2007
Top speed	144 mph
0 - 60 mph	7.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	400 Nm at 1.300 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-12-18
Pictures	13
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-04-08
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	21
Total items failed	15

MOT #20 2024-04-09 15:52

MOT test number 192319459885

Result ✓ Passed

Next expiry date 2025-04-08

Minor Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #19 2023-02-18 11:27

MOT test number 770579493337

Result ✓ Passed

MOT #18 2022-02-25 11:11

MOT test number 910097368441

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17 2021-10-25 11:37

MOT test number 935935310507

Result ✓ Passed

**MOT #16**

2020-11-05 17:03

MOT test number

739615452912

Result

✓ Passed

Minor Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Undertrays fitted**Minor** Offside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**MOT #15**

2020-10-22 09:14

MOT test number

541814106817

Result

✗ Failed

Fail Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Offside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Undertrays fitted**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #14**

2019-05-09 08:11

MOT test number

606320425286

Result

✓ Passed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #13**

2018-05-24 16:44

MOT test number

930491761929

Result

✓ Passed

**MOT #12** 2018-05-18 15:51**MOT test number** 152124357147**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #11** 2017-05-20 10:01**MOT test number** 945472080656**Result** ✓ Passed**MOT #10** 2017-05-20 09:08**MOT test number** 657306105531**Result** ✗ Failed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #9** 2016-04-26 13:26**MOT test number** 800071034843**Result** ✓ Passed**MOT #8** 2016-04-20 15:38**MOT test number** 475492796104**Result** ✗ Failed**Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #7** 2015-08-22 11:28**MOT test number** 265646890033**Result** ✓ Passed**MOT #6** 2015-08-21 10:48**MOT test number** 572896592487**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2014-03-20 18:28**MOT test number** 806329274094**Result** ✓ Passed**MOT #4** 2014-02-01 12:08**MOT test number** 129172234070**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-12-17 17:09**MOT test number** 345092652323**Result** ✓ Passed



MOT #2	2011-12-29 10:50
MOT test number	948643161323
Result	✓ Passed
Notice	Both front tyres worn on sholders
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Service overdue light on

MOT #1	2011-01-06 15:15
MOT test number	448786801062
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
8 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-11-08
Last registration	2024-04-09
Complete history	See info



Registration #1	2007-11-08	6 mi
Registration #2	2011-01-06	68.510 mi
Registration #3	2011-12-29	73.550 mi
Registration #4	2012-12-17	78.338 mi
Registration #5	2014-02-01	85.182 mi
Registration #6	2014-03-20	85.212 mi
Registration #7	2015-08-21	101.436 mi
Registration #8	2015-08-22	101.436 mi
Registration #9	2016-04-20	108.744 mi
Registration #10	2016-04-26	108.749 mi
Registration #11	2017-05-20	123.918 mi
Registration #12	2018-05-20	131.377 mi
Registration #13	2019-05-20	131.377 mi
Registration #14	2020-05-20	131.377 mi
Registration #15	2021-05-20	131.377 mi
Registration #16	2022-05-20	131.377 mi
Registration #17	2023-05-20	131.377 mi
Registration #18	2024-05-20	131.377 mi
Registration #19	2025-05-20	131.377 mi
Registration #20	2026-05-20	131.377 mi
Registration #21	2027-05-20	131.377 mi
Registration #22	2028-05-20	131.377 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1817 mm
Height	1418 mm
Length	4520 mm
Wheel base	2760 mm
Kerb weight	1675 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	27726660