



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO AUTHENTIQUE DCI 80
Colour	Blue
Year of manufacture	2005
Top speed	96 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	185 Nm at 1.750 rpm
Engine capacity	1.451 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-03
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-18
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	57
Total items failed	7

MOT #24	2023-07-19 16:03
MOT test number	774180966585
Result	✓ Passed
Next expiry date	2024-07-18
Advice	Rear axle corrosion
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Handbrake cables corroded
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #23** 2023-07-11 11:15**MOT test number** 382878487335**Result** ✗ Failed**MAJOR** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Handbrake cables corroded**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Front Service brake excessively binding both sides (1.2.1 (f))**Advice** Rear axle corrosion**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MOT #22** 2022-07-04 15:38**MOT test number** 137213239782**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear back box exhaust ruber

**MOT #21**

2022-07-04 10:25

MOT test number

214209471590

Result**✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Offside Front Steering rack has excessive free play detected at the steering wheel (steering rack fitted) (2.3 (a) (i))**DANGEROUS** Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear back box exhaust ruber**MAJOR** Nearside Front Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #20**

2021-06-25 13:52

MOT test number

826524940248

Result**✓ Passed****Advice** BOTH windscreen wipers lightly smearing**Advice** Two rear exhaust rubber mountings deteriorating**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Front Coil spring corroded at lower coil section (5.3.1 (b) (i))**Minor** Offside Front Brake hose slightly twisted (1.1.12 (b) (i))**Advice** Front registration plate has damage**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Rear Passenger seat(s) missing at time of test

**MOT #19**

2021-06-25 10:21

MOT test number

929684265973

Result**✗ Failed****MAJOR** Brake performance not tested due to suspension fail (1.2.1 (g))**Advice** Nearside Rear Passenger seat(s) missing at time of test**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** BOTH windscreen wipers lightly smearing**MAJOR** Fuel pipe insecure filler pipe securing clip detached (6.1.3 (a) (i))**Advice** Two rear exhaust rubber mountings deteriorating**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Front Brake hose slightly twisted (1.1.12 (b) (i))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Front Coil spring corroded at lower coil section (5.3.1 (b) (i))**Advice** Front registration plate has damage**MOT #18**

2020-07-15 13:37

MOT test number

259065817522

Result**✓ Passed****Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #17**

2020-07-08 08:20

MOT test number

205533446886

Result**✗ Failed****MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MAJOR** Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**DANGEROUS** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #16**

2019-07-11 11:18

MOT test number

908600420085

Result**✓ Passed****MOT #15**

2019-07-03 09:29

MOT test number

833580113004

Result**✗ Failed****Advice** Offside play in track rod end**MAJOR** Nearside Rear Brake pipe excessively damaged (1.1.11 (c))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #14** 2018-07-03 09:01**MOT test number** 291338098193**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #13** 2017-06-27 11:25**MOT test number** 820087102006**Result** ✓ Passed**MOT #12** 2017-06-22 09:38**MOT test number** 755178686674**Result** ✗ Failed**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Fail** Offside Front front brake binding (3.7.B.1)**MOT #11** 2016-07-22 15:36**MOT test number** 492213896932**Result** ✓ Passed**MOT #10** 2016-07-21 13:04**MOT test number** 362630188568**Result** ✗ Failed**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #9** 2015-05-29 08:56**MOT test number** 499659045146**Result** ✓ Passed

**MOT #8** 2014-05-02 11:49**MOT test number** 547082824103**Result** ✓ Passed**Notice** Offside front tyre slightly perished**MOT #7** 2012-10-18 10:09**MOT test number** 687462192285**Result** ✓ Passed**MOT #6** 2012-10-16 11:36**MOT test number** 908890492234**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Notice** Front discs corroded**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Front front brake binding (3.7.B.1)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #5** 2011-10-05 15:54**MOT test number** 725518571207**Result** ✓ Passed**MOT #4** 2010-10-11 09:21**MOT test number** 780834580218**Result** ✓ Passed**MOT #3** 2009-10-14 10:20**MOT test number** 674827189200**Result** ✓ Passed



MOT #2	2008-10-15 09:55
MOT test number	391789688225
Result	✓ Passed
MOT #1	2007-11-26 15:54
MOT test number	811410537390
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
18 July 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	18 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	2024-03-28
Agreement type	RENT TO BUY
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-05-31
Last registration	2023-07-19
Complete history	See info



Registration #1	2005-05-31	14 mi
Registration #2	2007-11-26	15.846 mi
Registration #3	2008-10-15	20.538 mi
Registration #4	2009-10-14	25.161 mi
Registration #5	2010-10-11	28.030 mi
Registration #6	2011-10-05	32.276 mi
Registration #7	2012-10-16	33.345 mi
Registration #8	2012-10-18	33.351 mi
Registration #9	2014-05-02	33.717 mi
Registration #10	2015-05-29	34.031 mi
Registration #11	2016-07-21	34.544 mi
Registration #12	2016-07-22	34.549 mi
Registration #13	2017-06-22	40.641 mi
Registration #14	2018-06-22	45.377 mi
Registration #15	2019-06-22	50.113 mi
Registration #16	2020-06-22	54.849 mi
Registration #17	2021-06-22	59.585 mi
Registration #18	2022-06-22	64.321 mi
Registration #19	2023-06-22	69.057 mi
Registration #20	2024-06-22	73.793 mi
Registration #21	2025-06-22	78.529 mi
Registration #22	2026-06-22	83.265 mi
Registration #23	2027-06-22	88.001 mi
Registration #24	2028-06-22	92.737 mi
Registration #25	2029-06-22	97.473 mi
Registration #26	2030-06-22	102.209 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2060 mm
Height	1827 mm
Length	3995 mm
Wheel base	2600 mm
Kerb weight	1095 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3

Engine number

D330971