



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 COUPE CABRIOLET S
Colour	Green
Year of manufacture	2003
Top speed	120 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.5 mpg
Consumption combined	40.3 mpg
CO2 emission	166 g/km
CO2 label	H









Internet history

Entry 1

Date	2021-09-01
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2023-09-06
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	56
Total items failed	15

MOT #24	2022-08-08 15:41
MOT test number	691452787944
Result	✓ Passed
Next expiry date	2023-09-06
Advice	Nearside Front Valve stem slightly damaged (5.2.3 (j))
Advice	Brake hose has slight corrosion to ferrule Both rears (1.1.12 (f) (i))
Advice	Offside Front Valve stem slightly damaged (5.2.3 (j))
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #23	2022-08-03 16:07
MOT test number	637645608849
Result	✗ Failed
Advice	Nearside Front Valve stem slightly damaged (5.2.3 (j))
Advice	Brake hose has slight corrosion to ferrule Both rears (1.1.12 (f) (i))
Advice	Offside Front Valve stem slightly damaged (5.2.3 (j))
Fail	Brake disc significantly and obviously worn Both fronts (1.1.14 (a) (i))
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #22** 2021-08-31 10:06**MOT test number** 983016489664**Result** ✓ Passed**MOT #21** 2020-09-07 13:17**MOT test number** 277584750964**Result** ✓ Passed

- Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Front carpet fouling foot control's
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Non obligatory mirror damaged
- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #20** 2019-04-08 11:48**MOT test number** 178426915713**Result** ✓ Passed

- Advice** Rear braking system only just passed test advise.
- Advice** Rear Brake pad(s) wearing thin very close to limit advise (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front carpet fouling foot controles.advise
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



<b>MOT #19</b>	2018-04-06 14:38
<b>MOT test number</b>	943720172777
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)
<b>Advice</b>	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #18</b>	2018-03-28 11:22
<b>MOT test number</b>	342115060138
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Fail</b>	Offside Rear rear parking brake recording little or no effort handbrake cable broken (3.7.B.6a)
<b>Fail</b>	Parking brake: efficiency below requirements (3.7.B.7)
<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)
<b>Fail</b>	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

<b>MOT #17</b>	2017-04-11 11:39
<b>MOT test number</b>	834594613515
<b>Result</b>	✓ Passed
<b>Advice</b>	Hand brake efficiency could be better

<b>MOT #16</b>	2017-04-11 11:39
<b>MOT test number</b>	400056758306
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Registration plate lamp not working (1.1.C.1d)
<b>Pass with rectification</b>	Nearside Registration plate lamp not working (1.1.C.1d)
<b>Advice</b>	Hand brake efficiency could be better
<b>Pass with rectification</b>	Nearside Rear position lamp(s) not working (1.1.A.3b)

**MOT #15** 2016-04-13 14:39**MOT test number** 161559583739**Result** ✓ Passed**MOT #14** 2015-04-16 16:17**MOT test number** 559296105163**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #13** 2014-04-15 16:21**MOT test number** 145235704128**Result** ✓ Passed**MOT #12** 2013-04-03 12:22**MOT test number** 345903093075**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2013-04-03 12:22**MOT test number** 978353493025**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Pass with rectification** Nearside Front suspension has a suspension lower ball joint securing nut loose (2.5.B.1a)

**MOT #10** 2012-04-13 11:02**MOT test number** 469454502180**Result** ✓ Passed**MOT #9** 2011-04-04 12:02**MOT test number** 527074191053**Result** ✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** N/s rear tyre has small cut in tread
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Front wipers slightly worn
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #8** 2010-04-06 14:32**MOT test number** 180326990431**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7**

2010-04-06 14:32

**MOT test number**

943686790051

**Result****✗ Failed****Pass with rectification**

Nearside Headlamp aim too high (1.8)

**Advice**

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Pass with rectification**

Offside Headlamp aim too high (1.8)

**Advice**

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6**

2009-04-07 16:20

**MOT test number**

973447699031

**Result****✓ Passed****Notice**

Rear brake pads getting low

**MOT #5**

2009-04-06 12:59

**MOT test number**

752366699012

**Result****✗ Failed****Fail**

Centre Exhaust has a major leak of exhaust gases (7.1.2)

**Fail**

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail**

Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**Notice**

Rear brake pads getting low

**MOT #4**

2008-04-10 12:32

**MOT test number**

112691308166

**Result****✓ Passed****Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice**

Offside door mirror casing broken.





MOT #3	2007-03-29 15:41
MOT test number	470958887015
Result	✓ Passed

MOT #2	2007-03-29 12:17
MOT test number	751238587044
Result	✗ Failed
<div><div>Notice</div>Nsr tyre cracking</div>	
<div><div>Notice</div>Front pads getting low discs worn</div>	
<div><div>Fail</div>Nearside Front Front position lamp(s) not working (1.1.A.3b)</div>	
<div><div>Notice</div>Osf indicator just showing white</div>	
<div><div>Notice</div>Rear pads very low</div>	
<div><div>Notice</div>Rear brake pipe clip broken</div>	
<div><div>Notice</div>Os mirror loose</div>	

MOT #1	2006-04-12 12:32
MOT test number	672112206104
Result	✓ Passed
<div><div>Advice</div>Offside Rear Brake pad(s) wearing thin (3.5.1g)</div>	



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	YK03WWL
Plate since	2019-03-29
Current registration	YK03WWL
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-04-17
Last registration	2022-08-08
Complete history	<a href="#">See info</a>



Registration #1	2003-04-17	28 mi
Registration #2	2006-04-12	18.728 mi
Registration #3	2007-03-29	23.260 mi
Registration #4	2007-03-29	23.262 mi
Registration #5	2008-04-10	29.097 mi
Registration #6	2009-04-06	33.359 mi
Registration #7	2009-04-07	33.359 mi
Registration #8	2010-04-06	37.354 mi
Registration #9	2011-04-04	41.753 mi
Registration #10	2012-04-13	46.308 mi
Registration #11	2013-04-03	50.235 mi
Registration #12	2014-04-15	55.379 mi
Registration #13	2015-04-15	59.379 mi
Registration #14	2016-04-15	63.379 mi
Registration #15	2017-04-15	67.379 mi
Registration #16	2018-04-15	71.379 mi
Registration #17	2019-04-15	75.379 mi
Registration #18	2020-04-15	79.379 mi
Registration #19	2021-04-15	83.379 mi
Registration #20	2022-04-15	87.379 mi
Registration #21	2023-04-15	91.379 mi
Registration #22	2024-04-15	95.379 mi
Registration #23	2025-04-15	99.379 mi
Registration #24	2026-04-15	103.379 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1673 mm
Height	1373 mm
Length	3835 mm
Wheel base	2442 mm
Kerb weight	1140 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	FX4W2122737