





### General information

| Make                | HONDA               |
|---------------------|---------------------|
| Model               | HR-V I-DTEC SE NAVI |
| Colour              | Blue                |
| Year of manufacture | -                   |
| Top speed           | 119 mph             |
| 0 - 60 mph          | 10.2 seconds        |
| Gearbox             | 6 speed Manual      |

# Engine & fuel consumption

| Power                   | 118 BHP             |
|-------------------------|---------------------|
| Max. torque             | 300 Nm at 2.000 rpm |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 64.2 mpg            |
| Consumption extra urban | 72.4 mpg            |
| Consumption combined    | 68.9 mpg            |



| ntry 1                     |   |           |   |
|----------------------------|---|-----------|---|
| Date                       | 2021-07-1   | 15        |   |
| lictures                   | 5   |           |   |
| isting price               | View repo   | <u>rt</u> |   |
| Approved Cars<br>& Finance | Cick & Deliver         Cick & Deliver         Complete your deal online or by phone.         The arrange of existing which is the bedward to set.         Cick warding which is the bedward to set. |           | THIS CAR COMES WITH<br>E 5225<br>OF FACTORY HITTED EXTRAS |

source: cargurus.co.uk



# MOT history

| MOT #8           | 2022-08-12 10:33 |
|------------------|------------------|
| MOT test number  | 848225069390     |
| Result           | ✓ Passed         |
| Next expiry date | 2023-08-17       |

| MOT #7  | 2022-08-12 09:01 |
|---|------------------|
| MOT test number   | 483870749624     |
| Result  | 🗙 Failed         |
| <b>Fail</b> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))       |                  |
| Fail         Electronic braking system warning device indicates a fault (1.7 (b)) |                  |

| МОТ #6          | 2021-08-17 14:41 |
|-----------------|------------------|
| MOT test number | 826002786472     |
| Result          | ✓ Passed         |

| MOT #5  | 2020-08-18 10:03 |
|---|------------------|
| MOT test number   | 875387884219     |
| Result  | ✓ Passed         |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| МОТ #4          | 2019-05-07 08:04 |
|-----------------|------------------|
| MOT test number | 712573891603     |
| Result          | ✓ Passed         |





| МОТ #3                  | 2019-05-07 08:04  |
|-------------------------|---|
| MOT test number         | 917985277629  |
| Result                  | × Failed  |
| Pass with rectification | Offside Headlamp aim too low (4.1.2 (a))                            |
| Pass with rectification | Offside Windscreen washer not working (3.5 (a))                     |
| Pass with rectification | Nearside Headlamp aim too low and too far to the right. (4.1.2 (a)) |
| Pass with rectification | Nearside Windscreen washer not working (3.5 (a))                    |

| MOT #2          | 2018-11-21 13:14 |
|-----------------|------------------|
| MOT test number | 809545708066     |
| Result          | ✓ Passed         |
|                 |                  |

| MOT #1  | 2018-11-21 12:23 |
|---|------------------|
| MOT test number   | 977385562152     |
| Result  | 🗙 Failed         |
| <b>Fail</b> Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))          |                  |
| <b>Minor</b> Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i)) |                  |





#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |          |              |
|----------|----------|--------------|
| Date     |          |              |
| Category |          | Lawer        |
| Туре     | (******* |              |
| Damage 2 |          | AMPLE        |
| Damage 2 |          | E CONTRACTOR |
| Date     |          |              |
| Category |          | AMP          |
| Туре     |          |              |

#### Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec |             |
|--|-------------|
| *************  |             |
| ********   |             |
| *******  |             |
| ************   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this HONDA had different number pla   | tes.        |
| Number of plates   |             |
| Current registration   |             |
| Plate since  |             |
| Carrent registration   |             |
| Plate since  |             |
|  | More info > |





#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 10         |
| First mileage registration | 2015-11-20 |
| Last registration          | 2022-08-12 |
| Complete history           | See info   |



| Registration #1  | 2015-11-20 | 24 mi      |
|------------------|------------|------------|
| Registration #2  | 2018-11-21 | 64.439 mi  |
| Registration #3  | 2018-11-21 | 64.439 mi  |
| Registration #4  | 2019-05-07 | 70.754 mi  |
| Registration #5  | 2019-05-07 | 70.754 mi  |
| Registration #6  |            | 11.777 est |
| Registration #7  |            | 11.777 mi  |
| Registration #8  |            | 11.777 esi |
| Registration #9  |            | 11.777 mi  |
| Registration #10 |            | 00.000 est |

More info >





# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 86%             |
| Children       | 79%             |
| Pedestrian     | 72%             |
| Safety systems | 71%             |
| Overall rating | 79%             |
| Video          | see crash video |



| Dimensions & weight                                    |                          |
|--|--------------------------|
| Width  | 1772 mm                  |
| Height   | 1605 mm                  |
| Length   | 4294 mm                  |
| Wheel base   | 2610 mm                  |
| Kerb weight  | 1404 kg                  |
| Max. allowed weight                                    | 1870 kg                  |
|  |                          |
| Additional information                                 |                          |
| Additional information Fuel tank capacity              | 50 I                     |
|  | 50 l<br>Direct Injection |
| Fuel tank capacity                                     |                          |
| Fuel tank capacity<br>Fuel delivery                    | Direct Injection         |
| Fuel tank capacity<br>Fuel delivery<br>Number of doors | Direct Injection<br>5    |