





report date: 2024-03-28

General information

Make	HYUNDAI
Model	VELOSTER GDI SPORT
Colour	Red
Year of manufacture	2012
Top speed	125 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F



CarCheck.co.uk page 1/12



EX12MKE

report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-14

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-01
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	6
Total items failed	4

MOT #13	2023-06-06 16:14
MOT test number	354537039485
Result	✓ Passed
Next expiry date	2024-07-01
Advice Nearside rear tyre is worn low (3mm).	

MOT #12	2023-06-06 11:09
MOT test number	466918271019
Result	X Failed
Advice Nearside rear tyre is worn low (3mm). Fail Nearside Steering rack gaiter missing or no longer prevents the ingress	s of dirt (2.1.3 (g) (ii))

MOT #11	2022-06-23 13:07
MOT test number	728960583194
Result	✓ Passed
MOT #10	2022-06-23 09:36
MOT test number	174329687021
Result	× Failed
Fail Rear Registration plate does not conform to the specified requirements (0.1 (d))	
Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

CarCheck.co.uk page 3/12



EX12MKE

report date: 2024-03-28

MOT test number 454774031050

Result ✓ Passed

MOT #8 2020-09-10 12:54

MOT test number 681161680634

Result

✓ Passed

MOT #7 2020-09-03 10:43

MOT test number 558513122503

Result X Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6 2019-08-27 13:46

MOT test number 272662699551

Result ✓ Passed

MOT #5 2018-08-13 09:10

MOT test number 142716790119

Result
✓ Passed

MOT #4 2018-01-10 13:02

MOT test number 720928908515

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/12



MOT #3 2017-04-05 12:30

MOT test number 704107384754

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #2 2016-04-20 09:08

MOT test number 784514386839

Result ✓ Passed

MOT #1 2015-04-18 11:10

MOT test number 656268505142

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	1 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



EX12MKE

report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

EX12MKE

report date: 2024-03-28

More info >

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HYUNDAI had different number plates.

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-04-16
Last registration	2023-06-06
Complete history	See info



Registration #1	2012-04-16	23 mi
Registration #2	2015-04-18	19.464 mi
Registration #3	2016-04-20	23.766 mi
Registration #4	2017-04-05	28.585 mi
Registration #5	2018-01-10	33.398 mi
Registration #6	2018-08-13	38.257 mi
Registration #7	2019-08-27	42.579 mi
Registration #8	2020-09-03	48.747 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number G4FDBU724579