



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI
Colour	Silver
Year of manufacture	2011
Top speed	117 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	167 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-07-22
Pictures	44
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-04-04
<b>MOT pass rate</b>	67 %
<b>MOT passed</b>	10
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	57
<b>Total items failed</b>	21

**MOT #15** 2024-03-28 15:10**MOT test number** 630159708867**Result** ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Seat belt retracting mechanism defective (7.1.2 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge + cracking (5.2.3 (e))
- Fail** Offside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Rear Seat belt retracting mechanism defective (7.1.2 (e))

**MOT #14** 2023-04-05 14:16**MOT test number** 220152762379**Result** ✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))



MOT #13

2022-04-05 09:33

MOT test number

210089879233

Result

✓ Passed

- Advice

Coil spring corroded Nearside and offside rear (5.3.1 (b) (i))
- Advice

Oil leak, but not excessive From engine (8.4.1 (a) (i))
- Advice

Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice

Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside rear (1.1.14 (a) (ii))
- Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

All exhaust corroded but supported
- Advice

Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #12**

2022-03-28 15:52

**MOT test number**

936343284851

**Result****✗ Failed**

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Coil spring corroded Nearside and offside rear (5.3.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside front (1.1.14 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** All exhaust corroded but supported
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Fail** Offside Front Tyre has ply or cords exposed On inner edge. 235/65r17 (5.2.3 (d) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Brake pad(s) less than 1.5 mm thick Nearside and offside front (1.1.13 (a) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside rear (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive From engine (8.4.1 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))



MOT #112021-02-24 10:33

MOT test number807321719064

Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn to limit bald inner edge (5.2.3 (e))	
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	

**MOT #10**

2021-02-23 15:57

**MOT test number**

767862751711

**Result**

✗ Failed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn to limit bald inner edge (5.2.3 (e))
- Fail** Offside Rear Rear reflector missing (4.8.2 (a) (ii))
- Advice** Oil level is very low
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9**

2019-03-07 13:52

**MOT test number**

523067098529

**Result**

✓ Passed

- Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #8** 2019-03-07 12:06**MOT test number** 353947938665**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #7** 2018-03-07 15:05**MOT test number** 109801695331**Result** ✓ Passed**MOT #6** 2017-08-17 08:27**MOT test number** 262968414125**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin both side (3.5.1g)
- Advice** Engine warning light on dash
- Advice** Front Brake pad(s) wearing thin both side (3.5.1g)
- Advice** Front Shock absorber has a light misting of oil both side (2.7.3)



**MOT #5** 2017-08-17 08:27**MOT test number** 413566235827**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin both side (3.5.1g)**Advice** Engine warning light on dash**Advice** Front Shock absorber has a light misting of oil both side (2.7.3)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Advice** Rear Brake pad(s) wearing thin both side (3.5.1g)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2016-08-03 13:18**MOT test number** 419384440786**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2015-08-03 11:38**MOT test number** 777575615231**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #2	2015-04-21 13:35
MOT test number	418531615101
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #1	2014-05-07 14:20
MOT test number	789367824130
Result	✓ Passed



Tax & MOT check

✓

Taxed

Tax due:  
1 March 2025

✗

MOT

Expired:  
4 April 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	4 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>BP11VDR</b>
Plate since	2024-03-29
Current registration	<b>BP11VDR</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-07-06
Last registration	2024-03-28
Complete history	<a href="#">See info</a>



Registration #1	2011-07-06	8 mi
Registration #2	2014-05-07	21.356 mi
Registration #3	2015-04-21	32.607 mi
Registration #4	2015-08-03	35.796 mi
Registration #5	2016-08-03	46.087 mi
Registration #6	2017-08-17	55.906 mi
Registration #7	2017-08-17	55.906 mi
Registration #8	2018-03-07	60.646 mi
Registration #9	2019-03-07	69.279 mi
Registration #10	2019-03-07	69.279 mi
Registration #11	2019-03-07	69.279 mi
Registration #12	2019-03-07	69.279 mi
Registration #13	2019-03-07	69.279 mi
Registration #14	2019-03-07	69.279 mi
Registration #15	2019-03-07	69.279 mi
Registration #16	2019-03-07	69.279 mi
Registration #17	2019-03-07	69.279 mi

More info >





Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1761 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	014067KX