



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	C C200K SE
Colour	Red
Year of manufacture	2008
Top speed	144 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	208 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-09-01
Pictures	41
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-14
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	19
Total items failed	15

MOT #21	2023-09-15 10:22
MOT test number	180987492996
Result	✓ Passed
Next expiry date	2024-09-14
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #20	2023-09-04 12:09
MOT test number	565428645210
Result	✗ Failed
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Side repeater not working (4.4.1 (a) (ii))

MOT #19	2022-08-15 14:16
MOT test number	493138121916
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened on inside (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened on inside (1.1.14 (a) (ii))

**MOT #18** 2022-08-05 11:13**MOT test number** 713304795908**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened on inside (1.1.14 (a) (ii))**Fail** Nearside Rear Brake pipe excessively corroded from flexi forwards (1.1.11 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened on inside (1.1.14 (a) (ii))**Advice** Offside Rear Nail in tyre**Fail** Offside Front Brake pipe excessively corroded from flexi inwards (1.1.11 (c))**Fail** Offside Rear Brake pipe excessively corroded above tank on nearside (1.1.11 (c))**MOT #17** 2021-09-04 12:50**MOT test number** 240086316725**Result** ✓ Passed**MOT #16** 2020-11-03 16:18**MOT test number** 767548262612**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15**

2020-10-26 16:35

MOT test number

980348667494

Result**✗ Failed**

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))

MOT #14

2019-04-30 14:01

MOT test number

979236705288

Result**✓ Passed****MOT #13**

2019-04-30 09:18

MOT test number

502314402193

Result**✗ Failed**

- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Rear Exhaust system insecure (6.1.2 (a))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #12

2018-05-04 09:07

MOT test number

906980988458

Result**✓ Passed**

**MOT #11** 2017-04-21 10:56**MOT test number** 342198314627**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2016-04-27 08:56**MOT test number** 682339704088**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2015-04-30 15:20**MOT test number** 877320425149**Result** ✓ Passed**MOT #8** 2015-04-30 15:20**MOT test number** 339750325131**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front Side repeater not working (1.4.A.2c)**MOT #7** 2014-05-08 15:29**MOT test number** 206148224140**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-05-08 13:05**MOT test number** 279538024187**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Side repeater not working (1.4.A.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-05-24 13:22**MOT test number** 257894743434**Result** ✓ Passed**MOT #4** 2013-05-24 13:22**MOT test number** 558144443143**Result** ✗ Failed**Pass with rectification** Offside Outer Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #3** 2012-06-21 16:36**MOT test number** 206693672421**Result** ✓ Passed**MOT #2** 2012-03-07 12:42**MOT test number** 107097662055**Result** ✓ Passed**MOT #1** 2011-03-10 11:36**MOT test number** 796999761083**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
14 September 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-01-31
Last registration	2023-09-15
Complete history	See info



Registration #1	2008-01-31	21 mi
Registration #2	2011-03-10	32.843 mi
Registration #3	2012-03-07	47.594 mi
Registration #4	2012-06-21	51.039 mi
Registration #5	2013-05-24	57.057 mi
Registration #6	2014-05-08	61.311 mi
Registration #7	2014-05-08	61.311 mi
Registration #8	2015-04-30	67.482 mi
Registration #9	2016-04-27	73.942 mi
Registration #10	2017-04-21	80.148 mi
Registration #11	2018-05-04	85.721 mi
Registration #12	2019-05-04	91.311 mi
Registration #13	2020-05-04	96.902 mi
Registration #14	2021-05-04	102.493 mi
Registration #15	2022-05-04	108.084 mi
Registration #16	2023-05-04	113.675 mi
Registration #17	2024-05-04	119.266 mi
Registration #18	2025-05-04	124.857 mi
Registration #19	2026-05-04	130.448 mi
Registration #20	2027-05-04	136.039 mi
Registration #21	2028-05-04	141.630 mi

More info >



Dimensions & weight

Width	1957 mm
Height	1406 mm
Length	4343 mm
Wheel base	2715 mm
Kerb weight	1465 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	27194030966360