



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	AURIS T SPIRIT
Colour	White
Year of manufacture	2011
Top speed	111 mph
0 - 60 mph	11.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	142 Nm at 4.400 rpm
Engine capacity	1.797 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	70.6 mpg
Consumption extra urban	70.6 mpg
Consumption combined	70.6 mpg
CO2 emission	93 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-05-20
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-24
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	22
Total items failed	8

MOT #15 2023-10-25 12:31

MOT test number 962892941215

Result ✓ Passed

Next expiry date 2024-10-24

Minor Front Suspension rod ball joint dust cover severely deteriorated both side (5.3.4 (b) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #14 2023-10-25 12:18

MOT test number 817779933020

Result ✗ Failed

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Minor Front Suspension rod ball joint dust cover severely deteriorated both side (5.3.4 (b) (i))

Fail Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #13 2022-10-26 14:08

MOT test number 237856250262

Result ✓ Passed

MOT #12 2021-11-16 13:00

MOT test number 946323757899

Result ✓ Passed

**MOT #11** 2020-11-11 10:14**MOT test number** 679796010315**Result** ✓ Passed

Advice Offside Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity (4.2.3 (b) (ii))

Advice Central exhaust bracket broken but exhaust still adequately supported

Advice Nearside Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity (4.2.3 (b) (ii))

Advice Rear exhaust bracket broken but exhaust still adequately supported

MOT #10 2019-11-18 11:14**MOT test number** 334015375540**Result** ✓ Passed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #9 2018-11-26 14:15**MOT test number** 617416177888**Result** ✓ Passed**MOT #8** 2018-10-08 11:25**MOT test number** 100566031893**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Both rear tyres are perished

**MOT #7** 2018-10-08 11:25**MOT test number** 220675427346**Result** ✗ Failed**Advice** Both rear tyres are perished**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #6** 2017-10-06 11:12**MOT test number** 913603428589**Result** ✓ Passed**Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Under-tray blocking view of some components**Advice** Rear tyres sidewalls cracking/perishing**MOT #5** 2016-10-13 12:18**MOT test number** 993788578730**Result** ✓ Passed**Advice** Engine cover & undertrays hiding some components**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Minor cuts on o/s/f & n/s/r tyres

**MOT #4** 2016-10-13 11:15**MOT test number** 820493501411**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Engine cover & undertrays hiding some components**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Minor cuts on o/s/f & n/s/r tyres**MOT #3** 2015-10-05 13:15**MOT test number** 618625410687**Result** ✓ Passed**MOT #2** 2014-10-02 16:49**MOT test number** 356835174224**Result** ✓ Passed**MOT #1** 2014-10-02 14:34**MOT test number** 648885174216**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
24 October 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-10-17
Last registration	2023-10-25
Complete history	See info



Registration #1	2011-10-17	19 mi
Registration #2	2014-10-02	33.855 mi
Registration #3	2014-10-02	33.855 mi
Registration #4	2015-10-05	37.632 mi
Registration #5	2016-10-13	42.432 mi
Registration #6	2016-10-13	42.432 mi
Registration #7	2017-10-06	48.752 mi
Registration #8	2018-10-08	57.594 mi
Registration #9	2018-10-08	57.594 mi
Registration #10	2019-10-01	59.377 mi
Registration #11	2019-10-01	59.377 mi
Registration #12	2019-10-01	59.377 mi
Registration #13	2019-10-01	59.377 mi
Registration #14	2019-10-01	59.377 mi
Registration #15	2019-10-01	59.377 mi
Registration #16	2019-10-01	59.377 mi
Registration #17	2019-10-01	59.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1510 mm
Length	4245 mm
Wheel base	2600 mm
Kerb weight	1420 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2ZRU354637