



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 E4 D S S40
Colour	Black
Year of manufacture	2005
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-05
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-13
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	23
Total items failed	11

MOT #21	2023-12-13 10:50
MOT test number	863994967074
Result	✓ Passed
Next expiry date	2024-12-13
Advice	Offside Front disc back plate corroded
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
Advice	Front Exhaust has a minor leak of exhaust gases front flexy pipe (6.1.2 (a))

**MOT #20**

2023-12-05 11:08

MOT test number

175851380088

Result**✗ Failed**

- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases front flexy pipe (6.1.2 (a))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front disc back plate corroded
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

MOT #19

2022-12-01 08:48

MOT test number

880236962271

Result**✓ Passed**

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #18

2021-12-14 14:57

MOT test number

169285142222

Result**✓ Passed****MOT #17**

2021-12-14 12:52

MOT test number

923567354129

Result**✗ Failed**

- Fail** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #16** 2020-11-18 10:55**MOT test number** 417329641333**Result** ✓ Passed**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Offside Rear tyre cracked**MOT #15** 2019-11-27 16:06**MOT test number** 837471019480**Result** ✓ Passed**MOT #14** 2019-11-27 09:46**MOT test number** 459369959917**Result** ✗ Failed**Fail** Nearside Rear Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MOT #13** 2018-11-14 15:42**MOT test number** 165741907433**Result** ✓ Passed**Advice** Offside Front Inner tyre wearing**MOT #12** 2018-11-13 10:09**MOT test number** 901683344761**Result** ✗ Failed**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Front Inner tyre wearing

**MOT #11** 2017-11-16 12:26**MOT test number** 286502632529**Result** ✓ Passed**Advice** O/s rear anti rollbar slight play in balljoint**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #10** 2017-11-15 10:53**MOT test number** 486958666512**Result** ✗ Failed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** O/s rear anti rollbar slight play in balljoint**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #9** 2016-11-14 13:20**MOT test number** 781692869918**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement bush at rear of arm (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement bush at rear of arm (2.4.G.2)**MOT #8** 2015-11-24 12:34**MOT test number** 997373366218**Result** ✓ Passed**MOT #7** 2014-11-27 12:34**MOT test number** 427661534479**Result** ✓ Passed

**MOT #6** 2013-11-15 11:21**MOT test number** 445389213407**Result** ✓ Passed**MOT #5** 2012-11-27 11:23**MOT test number** 617872932351**Result** ✓ Passed**MOT #4** 2011-12-13 13:45**MOT test number** 305247941393**Result** ✓ Passed**Notice** Sills have covers unable to fully check condition**MOT #3** 2010-10-08 09:49**MOT test number** 922881980290**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2009-10-22 09:59**MOT test number** 340415999244**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2008-09-26 12:09**MOT test number** 404560178205**Result** ✓ Passed**Notice** Sills have covers unable to check condition



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
13 December 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	PE55TAU
Plate since	2024-03-28
Current registration	PE55TAU
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-30
Last registration	2023-12-13
Complete history	See info



Registration #1	2005-09-30	29 mi
Registration #2	2008-09-26	29.664 mi
Registration #3	2009-10-22	34.431 mi
Registration #4	2010-10-08	40.408 mi
Registration #5	2011-12-13	44.870 mi
Registration #6	2012-11-27	48.251 mi
Registration #7	2013-11-15	52.201 mi
Registration #8	2014-11-27	55.866 mi
Registration #9	2015-11-24	59.573 mi
Registration #10	2016-11-14	62.999 mi
Registration #11	2017-11-15	65.869 mi
Registration #12	2017-11-16	65.876 mi
Registration #13	2018-11-16	65.877 mi
Registration #14	2018-11-16	65.877 mi
Registration #15	2018-11-16	65.877 mi
Registration #16	2018-11-16	65.877 mi
Registration #17	2018-11-16	65.877 mi
Registration #18	2018-11-16	65.877 mi
Registration #19	2018-11-16	65.877 mi
Registration #20	2018-11-16	65.877 mi
Registration #21	2018-11-16	65.877 mi
Registration #22	2018-11-16	65.877 mi
Registration #23	2018-11-16	65.877 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	4022605