



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Black
Year of manufacture	2007
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	143 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg
CO2 emission	182 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-17
Pictures	22
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-20
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	20
Total items failed	4

MOT #16	2024-02-21 10:47
MOT test number	732883894444
Result	✓ Passed
Next expiry date	2025-02-20

MOT #15	2023-01-24 16:48
MOT test number	247535476577
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2023-01-23 13:17
MOT test number	116337416761
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #13	2022-01-13 14:46
MOT test number	835128153615
Result	✓ Passed

**MOT #12** 2022-01-12 11:02**MOT test number** 270862427116**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #11** 2021-01-28 07:40**MOT test number** 305348936478**Result** ✓ Passed**Advice** Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))**Advice** Sill covers fitted**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2019-05-20 09:17**MOT test number** 268431696036**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #9** 2018-05-30 09:49**MOT test number** 103732912918**Result** ✓ Passed**Advice** Both front tyres have cuts in the tread

**MOT #8** 2017-06-03 14:24**MOT test number** 814150996788**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front tyres cracks in tread**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-05-20 14:09**MOT test number** 769603743452**Result** ✓ Passed**MOT #6** 2015-03-02 14:39**MOT test number** 548111165064**Result** ✓ Passed**MOT #5** 2014-02-21 11:03**MOT test number** 157262054497**Result** ✓ Passed**MOT #4** 2013-02-27 15:45**MOT test number** 865748653037**Result** ✓ Passed

**MOT #3** 2012-11-01 16:35**MOT test number** 475706402368**Result** ✓ Passed**Notice** Rear tyres badly perished**Notice** Nearside front tyre outer sidewall perished**Notice** Nail in nearside rear tyre**MOT #2** 2011-11-22 14:51**MOT test number** 497456021338**Result** ✓ Passed**Notice** All four tyres have cracking on the sidewall**Notice** Front brake discs corroded and lipped**MOT #1** 2010-11-26 09:37**MOT test number** 164280830374**Result** ✓ Passed**Notice** Nearside front brake discs outer edge corroded/pads good



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
20 February 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	20 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-11-27
Last registration	2024-02-21
Complete history	See info



Registration #1	2007-11-27	12 mi
Registration #2	2010-11-26	13.886 mi
Registration #3	2011-11-22	21.234 mi
Registration #4	2012-11-01	28.419 mi
Registration #5	2013-02-27	30.301 mi
Registration #6	2014-02-21	34.823 mi
Registration #7	2015-03-02	37.762 mi
Registration #8	2016-05-20	39.735 mi
Registration #9	2017-06-03	41.919 mi
Registration #10	2018-06-20	45.377 mi
Registration #11	2019-06-20	48.377 mi
Registration #12	2020-06-20	51.377 mi
Registration #13	2021-06-20	54.377 mi
Registration #14	2022-06-20	57.377 mi
Registration #15	2023-06-20	60.377 mi
Registration #16	2024-02-21	63.377 mi
Registration #17	2024-02-21	63.377 mi
Registration #18	2024-02-21	63.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1256 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4ED7871938