



KP60XEE

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC TDI CC DSG
Colour	Grey
Year of manufacture	2010
Top speed	139 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	8.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	103 kW / 140 HP / 170 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	158 g/km
CO2 label	G





MOT history

MOT expiry date	2025-02-12
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	41
Total items failed	0

MOT #12	2024-02-13 12:24
---------	------------------

MOT test number	779639139079
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-12
------------------	------------

Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Nail in tyre
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside cv boot clip loose

**MOT #11**

2024-02-01 12:54

**MOT test number**

680827033865

**Result****✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- MAJOR** Offside Front Headlamp levelling device inoperative (4.1.5 (a))
- Advice** Nearside Front Nail in tyre
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- MAJOR** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Offside cv boot clip loose
- MAJOR** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- DANGEROUS** Offside Rear Tyre has ply or cords exposed 235 40 18 (5.2.3 (d) (ii))
- MAJOR** Nearside Front Headlamp levelling device inoperative (4.1.5 (a))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Nearside Rear Headlamp levelling device inoperative (4.1.5 (a))
- MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- MAJOR** Offside Headlamp aim too high (4.1.2 (a))

**MOT #10**

2023-02-02 09:17

**MOT test number**

532648022246

**Result**

✓ Passed

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor** Nearside Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #9**

2022-01-31 09:28

**MOT test number**

955786621429

**Result**

✓ Passed

**MOT #8**

2021-02-03 10:37

**MOT test number**

577033355990

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7**

2020-01-06 14:48

**MOT test number**

185039604020

**Result**

✓ Passed

**Advice** Rear Shock absorbers light misting of oil or has limited damping effect N/S and O/S. (5.3.2 (b))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush. (5.3.4 (a) (i))



<b>MOT #6</b>	2018-11-20 09:51
---------------	------------------

<b>MOT test number</b>	621601383949
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2017-11-22 15:43
---------------	------------------

<b>MOT test number</b>	904053273816
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
---------------	---

<b>Advice</b>	Offside Rear Shock absorber has a light misting of oil (2.7.3)
---------------	--

<b>MOT #4</b>	2016-09-20 07:16
---------------	------------------

<b>MOT test number</b>	669565595325
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2015-10-20 11:34
---------------	------------------

<b>MOT test number</b>	985824498681
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-11-12 10:14
---------------	------------------

<b>MOT test number</b>	868406514367
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2013-11-20 10:40
---------------	------------------

<b>MOT test number</b>	638864423376
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
12 February 2025

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	217
<b>MOT expiry date</b>	12 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KP60XEE
Plate since	2019-06-29
Current registration	 KP60XEE
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-11-22
Last registration	2024-02-13
Complete history	<a href="#">See info</a>



Registration #1	2010-11-22	10 mi
Registration #2	2013-11-20	34.779 mi
Registration #3	2014-11-12	45.460 mi
Registration #4	2015-10-20	57.623 mi
Registration #5	2016-09-20	69.210 mi
Registration #6	2017-11-22	78.422 mi
Registration #7	2018-11-20	86.185 mi
Registration #8	2019-05-20	95.277 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1417 mm
Length	4799 mm
Wheel base	2708 mm
Kerb weight	1485 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

**Number of axles**

2

**Engine number**

CBA 748274