



VU63HTJ

report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER
Colour	Grey
Year of manufacture	2013
Top speed	124 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-03
Pictures	63
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-21
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	11
Total items failed	1

MOT #10	2023-06-19 10:29
MOT test number	709246699837
Result	✓ Passed
Next expiry date	2024-06-21

MOT #9	2022-06-16 08:42
MOT test number	424695900805
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8	2021-06-22 10:36
MOT test number	245485093882
Result	✓ Passed

MOT #7	2020-08-25 11:22
MOT test number	723634347162
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2019-08-16 15:36**MOT test number** 918248266217**Result** ✓ Passed**MOT #5** 2019-08-16 15:08**MOT test number** 535979922719**Result** ✗ Failed

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Items removed from driver's view prior to test

MOT #4 2018-08-24 09:14**MOT test number** 665217635449**Result** ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2-3mm (5.2.3 (e))

Advice Offside Rear Nail in tyre

Advice Offside Front Oil leak, but not excessive drive shaft seal slight leak (8.4.1 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2-4mm (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2-2.5mm (5.2.3 (e))

MOT #3 2017-08-25 09:35**MOT test number** 353031116481**Result** ✓ Passed**MOT #2** 2017-08-25 08:27**MOT test number** 734331564282**Result** ✗ Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #1	2016-08-24 12:44
MOT test number	885001923879
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
21 June 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-03-29
Current registration	 
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-01
Last registration	2023-06-19
Complete history	See info



Registration #1	2013-09-01	9 mi
Registration #2	2016-08-24	26.477 mi
Registration #3	2017-08-25	30.814 mi
Registration #4	2017-08-25	30.814 mi
Registration #5	2018-08-24	33.764 mi
Registration #6	2019-08-16	36.293 mi
Registration #7	2020-06-22	38.277 mi
Registration #8	2021-06-22	40.277 mi
Registration #9	2022-06-22	42.277 mi
Registration #10	2023-06-19	44.277 mi
Registration #11	2023-06-19	44.277 mi
Registration #12	2023-06-19	44.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1892 mm
Height	1384 mm
Length	3728 mm
Wheel base	2467 mm
Kerb weight	1120 kg
Max. allowed weight	1410 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2

Engine number	A437J422
---------------	----------