



report date: 2024-03-28

General information

Make	MAZDA
Model	3 D SPORT
Colour	Silver
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.183 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-27
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	72
Total items failed	7

MOT #21	2023-05-10 11:48
---------	------------------

MOT test number	406084329691
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-05-27
------------------	------------

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** DPF Light flashing
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Engine covers & under trays fitted obscuring some components
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #20**

2023-05-08 13:02

**MOT test number**

464888777371

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- MAJOR** Brake pedal has insufficient reserve travel (1.1.2 (a))
- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Engine covers & under trays fitted obscuring some components
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** DPF Light flashing
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #19**

2022-05-27 10:59

**MOT test number**

791362049414

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2022-05-26 10:49

**MOT test number**

273873307945

**Result****✗ Failed**

- MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (ii))

**MOT #17**

2021-05-28 08:09

**MOT test number**

619499346784

**Result****✓ Passed**

- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #16**

2020-03-10 14:16

**MOT test number**

739583392692

**Result****✓ Passed****MOT #15**

2020-03-09 11:49

**MOT test number**

101240482824

**Result****✗ Failed**

- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm 205/50/17 (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #14** 2019-07-09 08:04**MOT test number** 921685985586**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre worn outer edge (5.2.3 (e))**Advice** Undertrays fitted unable to fully inspect**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre worn outer edge (5.2.3 (e))**MOT #13** 2019-07-09 08:04**MOT test number** 452096806392**Result** ✗ Failed**Advice** Undertrays fitted unable to fully inspect**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre worn outer edge (5.2.3 (e))**Pass with rectification** Offside Steering locking device missing track rod end locking device (2.1.3 (d))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre worn outer edge (5.2.3 (e))**MOT #12** 2019-02-21 12:04**MOT test number** 795006642599**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e))**MOT #11** 2019-02-21 08:49**MOT test number** 473266689384**Result** ✗ Failed**MAJOR** Stop lamp(s) not working high level (4.3.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #10** 2018-02-27 15:39**MOT test number** 185145523325**Result** ✓ Passed**Advice** Under trays fitted**MOT #9** 2018-02-26 15:56**MOT test number** 986419454266**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Under trays fitted**MOT #8** 2017-08-09 11:22**MOT test number** 763266375290**Result** ✓ Passed**Advice** Offside front tyre worn uneven**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside front tyre worn uneven**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)

**MOT #7**

2017-08-09 08:38

**MOT test number**

508268912157

**Result****✗ Failed**

- Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)
- Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside front tyre worn uneven
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside front tyre worn uneven
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6**

2016-08-09 08:29

**MOT test number**

381857285687

**Result****✓ Passed**

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #5**

2016-08-09 08:29

**MOT test number**

941933865839

**Result****✗ Failed**

- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



**MOT #4** 2015-08-11 15:01**MOT test number** 278623825289**Result** ✓ Passed**MOT #3** 2014-08-13 12:50**MOT test number** 166545024249**Result** ✓ Passed**MOT #2** 2013-08-27 13:51**MOT test number** 487209533290**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2013-08-27 09:39**MOT test number** 835319833289**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
27 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	27 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2010-09-01
Last registration	2023-05-10
Complete history	<a href="#">See info</a>



Registration #1	2010-09-01	24 mi
Registration #2	2013-08-27	30.138 mi
Registration #3	2013-08-27	30.139 mi
Registration #4	2014-08-13	41.580 mi
Registration #5	2015-08-11	51.543 mi
Registration #6	2016-08-09	61.653 mi
Registration #7	2016-08-09	61.653 mi
Registration #8	2017-08-09	73.896 mi
Registration #9	2017-08-09	73.896 mi
Registration #10	2018-02-26	79.844 mi
Registration #11	2018-02-27	79.846 mi
Registration #12	2019-02-21	83.933 mi
Registration #13	2019-05-20	85.277 mi
Registration #14	2019-05-20	85.277 mi
Registration #15	2019-05-20	85.277 mi
Registration #16	2019-05-20	85.277 mi
Registration #17	2019-05-20	85.277 mi
Registration #18	2019-05-20	85.277 mi
Registration #19	2019-05-20	85.277 mi
Registration #20	2019-05-20	85.277 mi
Registration #21	2019-05-20	85.277 mi
Registration #22	2019-05-20	85.277 mi
Registration #23	2019-05-20	85.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4490 mm
Wheel base	2640 mm
Kerb weight	1453 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10249137