




report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	Black
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 2



Date	2021-07-22
Pictures	17
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-21
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-24
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	14
Total items failed	7

MOT #14 2023-10-13 15:08

MOT test number 585857111395

Result ✓ Passed

Next expiry date 2024-10-24

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #13 2023-10-13 13:56

MOT test number 612539963228

Result ✗ Failed

- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2022-10-25 15:11

MOT test number 841682260993

Result ✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))



MOT #11	2022-10-19 15:10
MOT test number	478127809734
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Parking brake inoperative on one side (1.4.1 (a))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #10	2021-10-21 15:21
MOT test number	517880482951
Result	✓ Passed

MOT #9	2021-10-21 12:13
MOT test number	153202375345
Result	✗ Failed
Fail	Nearside Headlamp aim too high (4.1.2 (a))
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #8	2020-09-18 09:01
MOT test number	947186460766
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner tread (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner tread (5.2.3 (e))



MOT #7 2019-10-02 09:08

MOT test number 622864086141

Result ✓ Passed

MOT #6 2018-10-29 10:34

MOT test number 351983377958

Result ✓ Passed

MOT #5 2017-11-14 10:43

MOT test number 904445226222

Result ✓ Passed

MOT #4 2016-11-07 13:52

MOT test number 143847134551

Result ✓ Passed

MOT #3 2015-11-03 11:04

MOT test number 667960533180

Result ✓ Passed

MOT #2 2014-11-12 10:34

MOT test number 418646314366

Result ✓ Passed

Notice O/s/f tyre worn on inner edge

MOT #1 2013-11-27 15:06

MOT test number 527091833321

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
24 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-12-30
Last registration	2023-10-13
Complete history	See info



Registration #1	2010-12-30	24 mi
Registration #2	2013-11-27	35.972 mi
Registration #3	2014-11-12	48.881 mi
Registration #4	2015-11-03	62.012 mi
Registration #5	2016-11-07	72.066 mi
Registration #6	2017-11-14	82.356 mi
Registration #7	2018-10-29	91.547 mi
Registration #8	2019-10-02	97.004 mi
Registration #9	2020-09-18	103.703 mi
Registration #10	2021-09-02	110.377 mi
Registration #11	2022-09-02	117.051 mi
Registration #12	2023-09-02	123.725 mi
Registration #13	2023-09-02	130.399 mi
Registration #14	2023-09-02	137.073 mi
Registration #15	2023-09-02	143.747 mi
Registration #16	2023-09-02	150.421 mi
Registration #17	2023-09-02	157.095 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1361361