



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF MATCH FSI 115
Colour	Black
Year of manufacture	2008
Top speed	119 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	155 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	161 g/km
CO2 label	G





## MOT history

MOT expiry date	2024-12-22
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	48
Total items failed	12

MOT #19 2023-12-21 15:33

MOT test number 351712712724

Result ✓ Passed

Next expiry date 2024-12-22

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Front Anti-roll bar linkage ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

MOT #18 2023-12-21 14:31

MOT test number 165792053819

Result ✗ Failed

- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Front Anti-roll bar linkage ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #17** 2022-12-20 16:11**MOT test number** 273934432188**Result** ✓ Passed**Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Minor** Offside Front Lower Windscreen damaged but not adversely affecting driver's view chipped (3.2 (a) (i))**MOT #16** 2021-12-20 12:47**MOT test number** 119373181945**Result** ✓ Passed**Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #15** 2020-12-15 15:26**MOT test number** 896118560842**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2019-12-23 13:04**MOT test number** 380198567195**Result** ✓ Passed**Minor** Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))

**MOT #13** 2018-12-14 15:29**MOT test number** 243964399063**Result** ✓ Passed**MOT #12** 2018-12-13 16:22**MOT test number** 890413919912**Result** ✗ Failed**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**MOT #11** 2017-12-02 14:19**MOT test number** 960814499552**Result** ✓ Passed**Advice** Engine cover fitted**Advice** Nearside Front Brake hose slightly chafed (3.6.B.4d)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2016-12-07 08:58**MOT test number** 718158854119**Result** ✓ Passed**Advice** Near side rear child seat fitted**Advice** Near side rear tyre nail**Advice** Near side front tyre side wall damaged

**MOT #9** 2016-12-06 10:06**MOT test number** 567344449903**Result** ✗ Failed**Fail** Nearside Front Braking system leaking (3.6.A.1)**Advice** Near side front tyre side wall damaged**Advice** Near side rear child seat fitted**Advice** Near side rear tyre nail**MOT #8** 2015-12-05 16:14**MOT test number** 590914889063**Result** ✓ Passed**Advice** Offside rear tyre has slight cracks on tread**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2015-12-05 13:57**MOT test number** 707897303198**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside rear tyre has slight cracks on tread**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nail in offside front tyre

**MOT #6** 2014-12-08 15:12**MOT test number** 346612844312**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Both front wipers is smearing**MOT #5** 2013-12-10 17:01**MOT test number** 745404443331**Result** ✓ Passed**Notice** Near side front tyre cracking on tread**Notice** Off side rear tyre cracking on tread**MOT #4** 2013-12-04 14:24**MOT test number** 497098133446**Result** ✗ Failed**Notice** Off side rear tyre cracking on tread**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Front passenger door cannot be opened from inside the vehicle (6.2.B.1b)**Notice** Near side front tyre cracking on tread**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)

**MOT #3** 2012-12-06 15:04**MOT test number** 408201242397**Result** ✓ Passed

- Notice** Off side rear tyre cut on tread
- Notice** Off side front tyre cracking on tread
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #2** 2012-12-06 12:48**MOT test number** 236951942335**Result** ✗ Failed

- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Off side rear tyre cut on tread
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Off side front tyre cracking on tread
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #1** 2011-08-25 15:05**MOT test number** 408517631281**Result** ✓ Passed

- Notice** Plenium chamber has leaves in it
- Notice** N/S/R tyre has screw in tyre tread punture



Tax & MOT check

X

Untaxed

Tax expired:  
21 February 2024

✓

MOT

Expires:  
22 December 2024

Tax status	Expired at 21 February 2024
Days left	68 days too late
MOT expiry date	22 December 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-09-01
Last registration	2023-12-21
Complete history	<a href="#">See info</a>



Registration #1	2008-09-01	29 mi
Registration #2	2011-08-25	9.626 mi
Registration #3	2012-12-06	13.061 mi
Registration #4	2012-12-06	13.061 mi
Registration #5	2013-12-04	14.657 mi
Registration #6	2013-12-10	14.679 mi
Registration #7	2014-12-08	19.072 mi
Registration #8	2015-12-05	22.691 mi
Registration #9	2015-12-05	22.691 mi
Registration #10	2016-12-06	27.359 mi
Registration #11	2016-12-06	27.359 mi
Registration #12	2016-12-06	27.359 mi
Registration #13	2016-12-06	27.359 mi
Registration #14	2016-12-06	27.359 mi
Registration #15	2016-12-06	27.359 mi
Registration #16	2016-12-06	27.359 mi
Registration #17	2016-12-06	27.359 mi
Registration #18	2016-12-06	27.359 mi
Registration #19	2016-12-06	27.359 mi
Registration #20	2016-12-06	27.359 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1359 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	BLF 450147