




report date: 2024-03-28

## General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	Silver
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C








Internet history

Entry 1

Date	2021-09-23
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk





MOT history

MOT expiry date	2024-10-29
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	22
Total items failed	4

MOT #11	2023-10-27 07:57
MOT test number	699905394853
Result	✓ Passed
Next expiry date	2024-10-29
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2023-10-21 08:33
MOT test number	397835005729
Result	✗ Failed
Fail	Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Drive shaft joint worn, but not excessively (6.1.7 (c) (i))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))



**MOT #9** 2022-10-25 08:35**MOT test number** 346861720935**Result** ✓ Passed**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #8** 2021-10-29 14:18**MOT test number** 467221086189**Result** ✓ Passed**MOT #7** 2020-10-20 14:28**MOT test number** 522025375979**Result** ✓ Passed**Advice** Both front tyres wearing inner edge**Advice** Offside Rear Nail in tyre**MOT #6** 2020-10-20 14:28**MOT test number** 214819710487**Result** ✗ Failed**Advice** Both front tyres wearing inner edge**Advice** Offside Rear Nail in tyre**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #5** 2019-10-30 08:45**MOT test number** 271694034022**Result** ✓ Passed**Advice** Both front tyres wearing inner edge



**MOT #4**

2018-10-18 14:19

**MOT test number**

396541930943

**Result**

✓ Passed

**Advice** Brake pad(s) wearing thin Both side front and rear pad running low (all are well above the legal limit) (1.1.13 (a) (ii))

**MOT #3**

2017-10-11 13:29

**MOT test number**

334085112575

**Result**

✓ Passed

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #2**

2016-07-28 16:29

**MOT test number**

624760045660

**Result**

✓ Passed

**Advice** Nearside Front tyre worn on edges

**Advice** Offside Front tyre worn on edges

**MOT #1**

2016-07-27 16:07

**MOT test number**

572032965229

**Result**

✗ Failed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front tyre worn on edges

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Offside Front tyre worn on edges





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
29 October 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	29 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-






Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-06-30
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2011-06-30	29 mi
Registration #2	2016-07-27	36.353 mi
Registration #3	2016-07-28	36.539 mi
Registration #4	2017-10-11	43.317 mi
Registration #5	2018-10-18	47.877 mi
Registration #6	2019-10-30	52.439 mi
Registration #7	2020-10-20	56.140 mi
Registration #8	2021-10-20	59.841 mi
Registration #9	2022-10-20	63.542 mi
Registration #10	2023-10-20	67.243 mi
Registration #11	2023-10-20	70.944 mi
Registration #12	2023-10-20	74.645 mi
Registration #13	2023-10-20	78.346 mi

More info >





Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4



<b>Number of axles</b>	2
<b>Engine number</b>	1708102