



RENAULT



R260MB


report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE RENAULTSPORT F1TEAM R26
Colour	Yellow
Year of manufacture	2007
Top speed	147 mph
0 - 60 mph	6.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	230 BHP
Max. torque	310 Nm at 3.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.1 mpg
CO2 emission	200 g/km
CO2 label	J





Internet history

Entry 3

Date	2021-09-29
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-09-28
Pictures	13
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-08-18
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-28
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	25
Total items failed	6

MOT #17	2023-09-29 10:27
MOT test number	266946898279
Result	✓ Passed
Next expiry date	2024-09-28
Advice	Engine oil leak
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #16	2022-09-28 13:44
MOT test number	745013711054
Result	✓ Passed

MOT #15	2022-09-23 15:37
MOT test number	186915897646
Result	✗ Failed
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MOT #14	2021-07-27 09:54
MOT test number	326496304087
Result	✓ Passed

**MOT #13** 2020-07-25 11:04**MOT test number** 614829148357**Result** ✓ Passed**MOT #12** 2019-09-10 14:00**MOT test number** 499189526597**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front brake pads getting low**MOT #11** 2019-09-09 16:21**MOT test number** 608366780578**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Front brake pads getting low**MOT #10** 2018-09-13 10:20**MOT test number** 131907876606**Result** ✓ Passed**Advice** Play in offside track rod end**Advice** Both front tyres worn to limit

**MOT #9** 2018-03-28 10:23**MOT test number** 297951789236**Result** ✓ Passed**Advice** Slight play in offside front steering /suspension**Advice** Front tyre treads low**MOT #8** 2018-03-28 10:23**MOT test number** 837322916476**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Front tyre treads low**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Slight play in offside front steering /suspension**MOT #7** 2017-03-24 09:55**MOT test number** 511965409459**Result** ✓ Passed**Advice** Front brake pads getting low**Advice** Rear tyre treads low**MOT #6** 2016-04-01 07:38**MOT test number** 991107066553**Result** ✓ Passed**Advice** Front tyres worn close to legal limit

**MOT #5** 2015-01-26 14:32**MOT test number** 785366425057**Result** ✓ Passed

- Advice** Offside Front constant velocity joint is slightly worn (2.5.C.1b)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front constant velocity joint is slightly worn (2.5.C.1b)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #4 2013-10-28 13:02**MOT test number** 499121303442**Result** ✓ Passed**MOT #3** 2012-10-27 12:29**MOT test number** 106971202389**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2011-10-25 15:16**MOT test number** 528898691275**Result** ✓ Passed



MOT #1	2010-10-26 09:29
MOT test number	201379590257
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
28 September 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	28 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-10-26
Last registration	2023-09-29
Complete history	See info



Registration #1	2007-10-26	8 mi
Registration #2	2010-10-26	13.789 mi
Registration #3	2011-10-25	17.534 mi
Registration #4	2012-10-27	20.304 mi
Registration #5	2013-10-28	23.323 mi
Registration #6	2015-01-26	30.709 mi
Registration #7	2016-04-01	36.698 mi
Registration #8	2017-03-24	44.794 mi
Registration #9	2018-03-28	54.736 mi
Registration #10	2018-03-28	54.736 mi
Registration #11	2018-09-13	58.749 mi
Registration #12	2019-03-29	58.749 mi
Registration #13	2019-03-29	58.749 mi
Registration #14	2019-03-29	58.749 mi
Registration #15	2019-03-29	58.749 mi
Registration #16	2019-03-29	58.749 mi
Registration #17	2019-03-29	58.749 mi
Registration #18	2019-03-29	58.749 mi
Registration #19	2019-03-29	58.749 mi
Registration #20	2019-03-29	58.749 mi
Registration #21	2019-03-29	58.749 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2617 mm
Kerb weight	1345 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	C016340