





report date: 2024-03-28

General information

Make	AUDI
Model	TT QUATTRO
Colour	Blue
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.7 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	250 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	3.189 сс
Cylinders	6
Fuel type	Petrol
Consumption city	21.9 mpg
Consumption extra urban	38.7 mpg
Consumption combined	30.1 mpg
CO2 emission	224 g/km
CO2 label	K



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-01-28

Pictures 6

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



M	OT^-	history
- 141	\circ	IIISLUIV

MOT expiry date	2024-09-08
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	15
Total items failed	7

MOT #17	2023-08-21 16:08
MOT test number	414541240508
Result	✓ Passed
Next expiry date	2024-09-08

MOT #16	2022-08-20 08:13
MOT test number	827667570488
Result	✓ Passed

MOT #15	2021-08-14 15:45
MOT test number	879993874570
Result	✓ Passed

MOT #14	2020-09-09 07:00
MOT test number	487459378898
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT test number
925683791936

Result
Advice Rear Inner Tyre worn close to legal limit/worn on edge Edges Worn (5.2.3 (e))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge Edge Bald (5.2.3 (e))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12

MOT test number

Result

Advice OFFSIDE FRONT TYRE BALD ON INNER EDGE

2018-09-04 11:16

384452012540

✓ Passed

MOT #11 2017-09-01 12:12 **MOT** test number 814375181695 Result Passed **MOT #10** 2017-08-31 14:53 **MOT** test number 809575342458 Result × Failed Fail Nearside Rear coil spring fractured (2.4.C.1a) Offside Rear coil spring broken (2.4.C.1a) Fail

MOT #9

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Under tray fitted

CarCheck.co.uk page 4/12



MOT #8 2016-08-16 11:51

MOT test number 346540394057

Result × Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm 245/40/zr18 (4.1.E.1)

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Offside Front Tyre has ply or cords exposed 245/40/zr 18 (4.1.D.1b)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Under tray fitted

MOT #7 2015-04-04 11:09

MOT test number 596594095019

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #6 2014-03-18 16:17

MOT test number 478567174012

Result ✓ Passed

MOT #5 2013-03-19 10:16

MOT test number 586058773001

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



MOT test number

Result

Pass with rectification

Offside Headlamp aim too high (1.8)

Pass with rectification

Nearside Headlamp aim too high (1.8)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3

MOT test number

815465772023

Result

Advice

Centre Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2

MOT test number

279335941050

Result

✓ Passed

 MOT #1
 2010-03-19 15:34

 MOT test number
 793838170026

 Result
 ✓ Passed

CarCheck.co.uk page 6/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	8 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/12



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	
HARMAN CO.	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK SIL
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-30
Last registration	2023-08-21
Complete history	See info



Registration #1	2007-03-30	11 mi
Registration #2	2010-03-19	25.445 mi
Registration #3	2011-02-14	32.738 mi
Registration #4	2012-03-15	42.039 mi
Registration #5	2013-03-19	48.573 mi
Registration #6	2014-03-18	53.211 mi
Registration #7	2015-04-04	58.704 mi
Registration #8	2016-08-16	65.227 mi
Registration #9	2016-08-17	65.227 mi
Registration #10		11.177 es
Registration #11		11.177 mi
Registration #12		11.177 es
Registration #13		11.177 es
Registration #14		11.177 es
Registration #15		11.177 es
Registration #16		0.00 44
Registration #17		11.177 ms
Registration #18		10.777 au

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1842 mm
Height	1352 mm
Length	4178 mm
Wheel base	2468 mm
Kerb weight	1430 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number BUB 039581