



GU62NFP


report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	White
Year of manufacture	2012
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	98 g/km
CO2 label	A





MOT history

MOT expiry date	2025-02-11
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	35
Total items failed	14

MOT #15 2024-02-12 10:27

MOT test number 476988932325

Result ✓ Passed

Next expiry date 2025-02-11

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Front Macpherson strut mounting damaged but not seriously weakened both sides (5.3.3 (b) (i))

MOT #14 2023-03-03 16:24

MOT test number 989701428882

Result ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2022-03-10 12:06

MOT test number

172991606799

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**MOT #12**

2021-03-18 11:02

MOT test number

628117813559

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #11**

2021-03-15 16:11

MOT test number

917771770228

Result

✗ Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

**MOT #10** 2020-08-21 11:30**MOT test number** 667191165572**Result** ✓ Passed

- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Front brake discs worn
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #9 2020-08-17 11:18**MOT test number** 610389262858**Result** ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Items removed from driver's view prior to test
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front brake discs worn
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #8 2019-09-02 12:00**MOT test number** 287171644129**Result** ✓ Passed

**MOT #7** 2019-06-17 10:55**MOT test number** 487246717282**Result** ✓ Passed**Advice** Grease around offside outer CV boot but no obvious signs of damage to gaiter**Advice** Exhaust mounting defective Centre to rear hanger broken (6.1.2 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn unevenly inner part**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2019-06-17 10:55**MOT test number** 455074727656**Result** ✗ Failed**Pass with rectification** Front All direction indicators incorrect colour (4.4.3 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn unevenly inner part**Advice** Exhaust mounting defective Centre to rear hanger broken (6.1.2 (a))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Grease around offside outer CV boot but no obvious signs of damage to gaiter**MOT #5** 2018-05-30 07:47**MOT test number** 253390864183**Result** ✓ Passed**Advice** Exhaust back box hanger broken**Advice** Offside Outer cv gaiter pin hole



MOT #4	2017-06-02 13:31
---------------	------------------

MOT test number	276980240503
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2017-06-02 13:31
---------------	------------------

MOT test number	120566588045
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Stop lamp not working (1.2.1b)
--------------------------------	--

MOT #2	2016-06-22 10:51
---------------	------------------

MOT test number	689098807926
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2015-10-21 09:18
---------------	------------------

MOT test number	605296677448
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
11 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	11 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-10-22
Last registration	2024-02-12
Complete history	See info



Registration #1	2012-10-22	17 mi
Registration #2	2015-10-21	22.233 mi
Registration #3	2016-06-22	26.897 mi
Registration #4	2017-06-02	34.756 mi
Registration #5	2017-06-02	34.756 mi
Registration #6	2018-05-30	43.307 mi
Registration #7	2019-06-17	50.966 mi
Registration #8	2019-06-17	50.966 mi
Registration #9	See info	See info
Registration #10	See info	See info
Registration #11	See info	See info
Registration #12	See info	See info
Registration #13	See info	See info
Registration #14	See info	See info
Registration #15	See info	See info
Registration #16	See info	See info

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBEJ0154815