



report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ3
Colour	White
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	93 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-12-18
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	20
Total items failed	4

MOT #12	2023-11-24 12:23
MOT test number	754168552777
Result	✓ Passed
Next expiry date	2024-12-18
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2022-12-19 15:12
MOT test number	407394897920
Result	✓ Passed
Minor	Nearside Front Outer Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Parking brake lever has near excessive travel, appears the braking system requires adjustment or repair but meets requirements
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Minor	Offside Front Outer Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Oil leak, but not excessive on gearbox output seal (8.4.1 (a) (i))

**MOT #10** 2022-12-19 15:12**MOT test number** 695371636189**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Oil leak, but not excessive on gearbox output seal (8.4.1 (a) (i))**Minor** Offside Front Outer Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Parking brake lever has near excessive travel, appears the braking system requires adjustment or repair but meets requirements**Minor** Nearside Front Outer Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #9** 2021-12-03 08:57**MOT test number** 598371769566**Result** ✓ Passed**MOT #8** 2021-12-03 08:57**MOT test number** 913225996143**Result** ✗ Failed**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #7** 2020-12-02 10:11**MOT test number** 307160160811**Result** ✓ Passed

**MOT #6** 2020-11-27 17:00**MOT test number** 314226004413**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #5** 2019-12-11 12:11**MOT test number** 945321026745**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust corroded at center to rear sections join**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2018-12-03 09:54**MOT test number** 457211482857**Result** ✓ Passed**MOT #3** 2017-12-02 12:05**MOT test number** 202074925164**Result** ✓ Passed**MOT #2** 2016-12-12 12:55**MOT test number** 291554905710**Result** ✓ Passed



MOT #1	2015-09-08 10:30
MOT test number	345516539575
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
18 December 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	18 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-28
Last registration	2023-11-24
Complete history	See info



Registration #1	2012-09-28	25 mi
Registration #2	2015-09-08	36.162 mi
Registration #3	2016-12-12	42.596 mi
Registration #4	2017-12-02	49.360 mi
Registration #5	2018-12-03	55.399 mi
Registration #6	2019-12-11	62.761 mi
Registration #7	2020-11-27	71.790 mi
Registration #8	2021-05-20	81.277 mi
Registration #9	2021-05-20	81.277 mi
Registration #10	2021-05-20	81.277 mi
Registration #11	2021-05-20	81.277 mi
Registration #12	2021-05-20	81.277 mi
Registration #13	2021-05-20	81.277 mi
Registration #14	2021-05-20	81.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1050 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	K12B-1407482