



RY07XHK


report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB P/V 130TDI
Colour	Beige
Year of manufacture	2007
Top speed	99 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
CO2 emission	251 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-07-09
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-01
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	35
Total items failed	22

MOT #19	2024-01-17 12:09
MOT test number	470686421220
Result	✓ Passed
Next expiry date	2025-02-01
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18	2023-02-02 15:48
MOT test number	618710301205
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17**

2023-01-31 14:46

MOT test number

800296667910

Result

✗ Failed

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn lower arm rear bush (5.3.4 (a) (i))**Advice** Front Headlamp has a product on the light source but not seriously reducing light output both clouded (4.1.4 (b))**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Suspension arm pin or bush excessively worn lower arm rear bush (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Rear fog lamp adversely affected by the operation of another lamp illuminates with position lamps (4.5.4 (b))**MOT #16**

2022-01-29 11:42

MOT test number

523082938716

Result

✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #15**

2022-01-28 14:21

MOT test number

576755779965

Result

✗ Failed

Fail Nearside Front Body component damaged and likely to cause injury MIRROR COVER DAMAGED HAS SHARP EDGES (6.2.1 (a) (i))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Front Windscreen washer not working (3.5 (a))

**MOT #14** 2021-02-01 09:46**MOT test number** 373353344461**Result** ✓ Passed**MOT #13** 2019-12-20 12:17**MOT test number** 468596366771**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Under tray fitted**MOT #12** 2018-08-03 08:28**MOT test number** 367270486825**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2017-07-25 13:33**MOT test number** 304984372732**Result** ✓ Passed**MOT #10** 2016-06-23 10:20**MOT test number** 487050941402**Result** ✓ Passed**Advice** Exhaust system in poor condition

**MOT #9** 2016-06-17 11:04**MOT test number** 975907230077**Result** ✗ Failed**Advice** Exhaust system in poor condition**Fail** Rear Tyre(s) incorrect because tyres fitted to all steerable axle are not of the same structure (4.1.A.2c)**Fail** Offside Front Direction indicator not working (1.4.A.2c)**Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2015-03-20 14:02**MOT test number** 818999575065**Result** ✓ Passed**MOT #7** 2013-09-24 14:27**MOT test number** 857857763239**Result** ✓ Passed**Notice** N/S/R/ TYRE SIDE WALLS SLIGHTLY CUT**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)



MOT #6 2013-09-24 14:27

MOT test number 859007863282

Result ✗ Failed

Pass with rectification Nearside Rear Stop lamp not working (1.2.1b)

Notice N/S/R/ TYRE SIDE WALLS SLIGHTLY CUT

Pass with rectification Offside Front Headlamp aim too low (1.8)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Under-trays fitted obscuring some underside components

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2012-09-01 14:54

MOT test number 465585742228

Result ✓ Passed

Notice Front brake disc slightly worn /pitted

Notice Centre /rear exhaust corroded

MOT #4 2012-09-01 14:54

MOT test number 836595542298

Result ✗ Failed

Pass with rectification Nearside Rear Stop lamp not working (1.2.1b)

Pass with rectification Offside Front Headlamp aim too low (1.8)

Notice Centre /rear exhaust corroded

Pass with rectification Offside Rear Stop lamp not working (1.2.1b)

Notice Front brake disc slightly worn /pitted



MOT #3

2011-08-23 10:17

MOT test number

556835431211

Result

✓ Passed

Notice

Front tyres worn

Notice

Damage to both sides of vehicle

Notice

Bushes

Notice

Rear tyre walls weak

MOT #2

2010-08-12 13:10

MOT test number

100164620237

Result

✓ Passed

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice

Rear brake pads slightly worn

MOT #1

2010-08-12 13:10

MOT test number

860054320204

Result

✗ Failed

Pass with rectification

Offside Rear Stop lamp not working (1.2.1b)

Pass with rectification

Nearside Rear Rear position lamp(s) not working (1.1.A.3b)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice

Rear brake pads slightly worn



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RY07XHK
Plate since	2024-03-29
Current registration	 RY07XHK
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-07-13
Last registration	2024-01-17
Complete history	See info



Registration #1	2007-07-13	20 mi
Registration #2	2010-08-12	21.787 mi
Registration #3	2011-08-23	30.368 mi
Registration #4	2012-09-01	37.445 mi
Registration #5	2013-09-24	47.399 mi
Registration #6	2015-03-20	65.000 mi
Registration #7	2016-06-17	70.401 mi
Registration #8	2016-06-23	70.401 mi
Registration #9	2017-07-25	70.488 mi
Registration #10	2019-05-20	70.577 mi
Registration #11	2019-05-20	70.577 mi
Registration #12	2019-05-20	70.577 mi
Registration #13	2019-05-20	70.577 mi
Registration #14	2019-05-20	70.577 mi
Registration #15	2019-05-20	70.577 mi
Registration #16	2019-05-20	70.577 mi
Registration #17	2019-05-20	70.577 mi
Registration #18	2019-05-20	70.577 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2242 mm
Height	2170 mm
Length	4890 mm
Kerb weight	1872 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	BNZ 064338