





report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D3 SE LUX AWD
Colour	Grey
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-12-25

Pictures 42

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Listing price

Date	2021-12-24
Pictures	1

View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



AX12KKM

report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-22
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	6
Total items failed	2

MOT #12	2024-01-16 11:21
MOT test number	474065519599
Result	✓ Passed
Next expiry date	2025-01-22

MOT #11	2023-01-11 11:17
MOT test number	325981803728
Result	✓ Passed

MOT #10	2023-01-10 10:07
MOT test number	437196098249
Result	X Failed
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #9	2022-01-07 09:44
MOT test number	686516979870
Result	✓ Passed

MOT #8	2021-01-12 13:48
MOT test number	822831878397
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #7 2021-01-12 10:11

MOT test number 326900963606

Result X Failed

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #6 2020-01-13 16:00

MOT test number 450461166681

Result \(\sqrt{Passed} \)

Advice Nearside Front tyre damaged at outer sidewall

Advice Some wear/corrosion rear discs

MOT #5 2019-01-08 15:33

MOT test number 484746531138

Result ✓ Passed

Advice Offside rear tyre perishing/cracking and cut in tread

Advice Both rear trailing arms front bushes separating/weakening

Advice Sweating to power steering pipe

Advice Nearside rear tyre perishing

MOT #4 2018-01-23 12:23

MOT test number 298050203267

Result ✓ Passed

MOT #3 2017-05-11 13:08

MOT test number 212409612803

Result

Passed

CarCheck.co.uk page 4/12



MOT #2 2016-04-06 10:31
MOT test number 126664601055

 MOT #1
 2015-04-30 12:31

 MOT test number
 226600125161

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	22 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.)
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		,
Current registration	UK CONTRACTOR	
Plate since		
Current registration	UK L	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-01
Last registration	2024-01-16
Complete history	See info



Registration #1	2012-05-01	9 mi
Registration #2	2015-04-30	24.569 mi
Registration #3	2016-04-06	31.997 mi
Registration #4	2017-05-11	38.987 mi
Registration #5	2018-01-23	42.568 mi
Registration #6	2019-01-08	50.476 mi
Registration #7	2020-01-13	59.297 mi
Registration #8	2021-01-12	62.747 mi
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1891 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles2Engine number1133407