




report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2013
Top speed	113 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.3 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-09-26
Pictures	20
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-25
Pictures	26
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-10-17
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	12
Total items failed	8

MOT #10 2022-10-18 12:47

MOT test number 168804571334

Result ✓ Passed

Next expiry date 2023-10-17

Advice Nearside Rear Nail in tyre

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2022-10-18 10:04

MOT test number 664327274726

Result ✗ Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Nail in tyre

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2021-06-30 13:13**MOT test number** 603129427918**Result** ✓ Passed**MOT #7** 2021-06-30 11:17**MOT test number** 433551000982**Result** ✗ Failed**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #6** 2019-05-03 08:54**MOT test number** 234855217221**Result** ✓ Passed**MOT #5** 2018-05-12 08:05**MOT test number** 262578678090**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #4** 2018-05-03 14:04**MOT test number** 837528688630**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)



MOT #3	2017-04-22 11:07
MOT test number	266020574930
Result	✓ Passed

MOT #2	2017-04-22 10:52
MOT test number	496371930259
Result	✗ Failed
<div><div>Fail</div>Offside Front position lamp(s) not working (1.1.A.3b)</div>	
<div><div>Fail</div>Nearside Front position lamp(s) not working (1.1.A.3b)</div>	
<div><div>Fail</div>Offside Registration plate lamp not working (1.1.C.1d)</div>	

MOT #1	2016-04-06 12:57
MOT test number	145352268103
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 December 2022

X

MOT

Expired:
17 October 2023

Tax status	Expired at 1 December 2022
Days left	514 days too late
MOT expiry date	17 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-23
Last registration	2022-10-18
Complete history	See info



Registration #1	2013-05-23	26 mi
Registration #2	2016-04-06	10.289 mi
Registration #3	2017-04-22	20.512 mi
Registration #4	2017-04-22	20.512 mi
Registration #5	2018-05-03	42.831 mi
Registration #6	2018-05-12	42.889 mi
Registration #7	2019-05-03	51.188 mi
Registration #8	2019-05-03	51.188 mi
Registration #9	2019-05-03	51.188 mi
Registration #10	2019-05-03	51.188 mi
Registration #11	2019-05-03	51.188 mi
Registration #12	2019-05-03	51.188 mi
Registration #13	2019-05-03	51.188 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1936 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 286966K LNQ