




report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	White
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-09
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	37
Total items failed	1

MOT #17	2024-03-04 11:27
MOT test number	873732620044
Result	✓ Passed
Next expiry date	2025-03-09
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #16	2023-03-02 12:16
MOT test number	281018919601
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #15** 2022-02-21 10:11**MOT test number** 358121412050**Result** ✓ Passed

- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14** 2021-03-10 09:05**MOT test number** 521826743024**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-09-24 10:47**MOT test number** 951050086312**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust flexi worn
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2020-07-04 11:44**MOT test number** 357406051913**Result** ✓ Passed

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11** 2019-06-25 12:02**MOT test number** 904300394143**Result** ✓ Passed



<b>MOT #10</b>	2019-06-24 15:18
<b>MOT test number</b>	254515823762
<b>Result</b>	✗ Failed
<b>MAJOR</b> Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	

<b>MOT #9</b>	2019-05-24 15:38
<b>MOT test number</b>	430514602379
<b>Result</b>	✓ Passed
<b>Advice</b> Offside Rear Shock absorbers light misting of oil or has limited damping effect Build up of oil around bottom of shock absorber and mounting point (5.3.2 (b))	
<b>Advice</b> Surface corrosion rear axle	
<b>Advice</b> Rear Road wheel slightly distorted Both rear wheels buckled (5.2.2 (c) (i))	
<b>Advice</b> Nearside Rear Rear tail light condensation build up	

<b>MOT #8</b>	2019-05-24 13:11
<b>MOT test number</b>	146731841735
<b>Result</b>	✗ Failed
<b>Advice</b> Offside Rear Shock absorbers light misting of oil or has limited damping effect Build up of oil around bottom of shock absorber and mounting point (5.3.2 (b))	
<b>Advice</b> Surface corrosion rear axle	
<b>Advice</b> Rear Road wheel slightly distorted Both rear wheels buckled (5.2.2 (c) (i))	
<b>MAJOR</b> Nearside Front Suspension arm ball joint excessively worn Excessive play NSF bottom ball joint (5.3.4 (a) (i))	
<b>Advice</b> Nearside Rear Rear tail light condensation build up	
<b>MAJOR</b> Rear Parking brake mechanism/associated mounting prescribed area is excessively corroded Handbrake cable mounting points excessively corroded/broken (1.1.21 (e) (i))	

<b>MOT #7</b>	2018-09-11 08:45
<b>MOT test number</b>	911786199621
<b>Result</b>	✓ Passed
<b>Advice</b> Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	

**MOT #6** 2017-08-31 13:38**MOT test number** 385719246065**Result** ✓ Passed**MOT #5** 2016-09-02 09:50**MOT test number** 356164839643**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-09-01 15:54**MOT test number** 518661909993**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #3** 2015-09-01 12:33**MOT test number** 527414145298**Result** ✓ Passed**Advice** Outer Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2014-08-26 10:03
MOT test number	385378134259
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Vehicle's internal headlight adjuster altered to recheck lights
Notice	Items removed from driver's view prior to test

MOT #1	2013-09-24 12:17
MOT test number	169617963204
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
9 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	9 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-





Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>PE60NUC</b>
Plate since	2024-03-28
Current registration	<b>PE60NUC</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-30
Last registration	2024-03-04
Complete history	<a href="#">See info</a>



Registration #1	2010-09-30	18 mi
Registration #2	2013-09-24	13.434 mi
Registration #3	2014-08-26	17.326 mi
Registration #4	2015-09-01	21.003 mi
Registration #5	2016-09-01	25.361 mi
Registration #6	2016-09-02	25.361 mi
Registration #7	2017-08-31	31.713 mi
Registration #8	2018-09-11	42.594 mi
Registration #9	2019-05-24	49.089 mi
Registration #10	2019-05-24	49.089 mi
Registration #11	2019-05-24	49.089 mi
Registration #12	2019-05-24	49.089 mi
Registration #13	2019-05-24	49.089 mi
Registration #14	2019-05-24	49.089 mi
Registration #15	2019-05-24	49.089 mi
Registration #16	2019-05-24	49.089 mi
Registration #17	2019-05-24	49.089 mi
Registration #18	2019-05-24	49.089 mi
Registration #19	2019-05-24	49.089 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5775203