





report date: 2024-03-29

General information

Make	VAUXHALL
Model	CORSA SRI VX-LINE NAV BLACK
Colour	Red
Year of manufacture	2019
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	43.5 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2022-01-12

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-12-02

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-30
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	23
Total items failed	5

MOT #5		2023-11-16 12:22
MOT test	number	469668999750
Result		✓ Passed
Next expi	ry date	2024-11-30
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))		
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	2023-11-15 16:01
MOT test number	133299408517
Result	× Failed
Fail Front Windscreen washer not working (3.5 (a))	
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail Offside Front Upper Macpherson strut attachment bracket/mounting insecure and in directional stability (5.3.3 (a) (ii))	mpairing
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #3 2022-11-10 12:11 **MOT test number** 537190713554 Result ✓ Passed Advice BOTH FRONT HEADLAMP AIMS ARE AT THERE HIGHEST ACCEPITABLE LEVEL Advice TPS LIGHT ON THE DASH ALL THE REAR WINDOWS ARE TINTED Advice Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt Advice Outer PLASTIC SILL COVERS Advice APPLIED FINGER AND THUMB PRESSURE ON SILLS AND FLOOR AREA Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT "O		2022 11 10 10 00
MOT #2		2022-11-10 10:09
MOT test	number	845948227052
Result		★ Failed
Fail 0	ffside Front Windscreen wiper does not clear the windscreen effectively A	AEROBLADE (3.4 (b) (ii))
Advice	APPLIED FINGER AND THUMB PRESSURE ON SILLS AND FLOOR AREA	
Advice	BOTH FRONT HEADLAMP AIMS ARE AT THERE HIGHEST ACCEPITABLE L	EVEL
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Fail N	earside Front Windscreen wiper does not clear the windscreen effectively	y AEROBLADE (3.4 (b) (ii))
Advice	TPS LIGHT ON THE DASH	
	earside Rear Tyre has a cut in excess of the requirements deep enough t (5.2.3 (d) (i))	to reach the ply or cords
Advice	ALL THE REAR WINDOWS ARE TINTED	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Outer PLASTIC SILL COVERS	

CarCheck.co.uk page 4/12



SF19CPP report date: 2024-03-29

MOT #1 2021-12-01 13:44

MOT test number 427958577198

Result ✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.


Damage 1

Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	





Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



SF19CPP report date: 2024-03-29

Owner history

Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	OK WE
Plate since	
Current registration	UK NAME OF THE PROPERTY OF THE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-06-24
Last registration	2023-11-16
Complete history	See info



Registration #1	2019-06-24	25 mi
Registration #2	2021-12-01	13.211 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		D.777 es
Registration #6		11.777 es
Registration #7		D.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	79%
Children	77%
Pedestrian	71%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1746 mm
Height	1481 mm
Length	4021 mm
Wheel base	2510 mm
Kerb weight	1102 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19VT0243LDD

CarCheck.co.uk page 12/12