



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Blue
Year of manufacture	2007
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 2

Date	2021-06-23
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-15
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-07-14
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	14
Total items failed	14

MOT #19	2022-07-15 17:39
MOT test number	859420854948
Result	✓ Passed
Next expiry date	2023-07-14
Advice	Rear Coil spring corroded Both rear (5.3.1 (b) (i))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #18**

2022-07-14 13:37

MOT test number

261053952982

Result

✗ Failed

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Coil spring corroded Both rear (5.3.1 (b) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Nearside Front Headlamp aim too low (4.1.2 (a))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #17**

2021-07-10 15:36

MOT test number

847875947537

Result

✓ Passed

MOT #16

2020-09-18 09:33

MOT test number

302300884196

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases Flexible section weeping (6.1.2 (a))**MOT #15**

2019-09-13 13:20

MOT test number

289080044483

Result

✓ Passed

**MOT #14** 2019-09-12 16:06**MOT test number** 266421868407**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #13** 2018-08-31 09:30**MOT test number** 705702683545**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Rear exhaust box outer skin deteriorated**MOT #12** 2018-08-31 09:30**MOT test number** 281096150341**Result** ✗ Failed**Advice** Rear exhaust box outer skin deteriorated**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Pass with rectification** Windscreen washer not working (3.5 (a))**MOT #11** 2017-09-13 15:18**MOT test number** 511355775818**Result** ✓ Passed**Advice** Offside Rear Tyre perished/cracked

**MOT #10** 2017-09-13 10:31**MOT test number** 986558586233**Result** ✗ Failed**Advice** Offside Rear Tyre perished/cracked**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #9** 2016-09-15 15:24**MOT test number** 221923443479**Result** ✓ Passed**MOT #8** 2016-09-12 14:05**MOT test number** 239694094204**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #7** 2016-02-10 12:16**MOT test number** 989953278062**Result** ✓ Passed**MOT #6** 2015-02-17 10:27**MOT test number** 168708645096**Result** ✓ Passed**MOT #5** 2014-02-17 12:47**MOT test number** 816738244030**Result** ✓ Passed



MOT #4	2013-02-15 13:01
MOT test number	769106143069
Result	✓ Passed

MOT #3	2012-02-13 13:18
MOT test number	616784342058
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2011-02-18 11:32
MOT test number	547049941043
Result	✓ Passed

MOT #1	2010-10-26 13:17
MOT test number	750179290277
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
28 February 2023

✕
MOT

Expired:
14 July 2023

Tax status	Expired at 28 February 2023
Days left	426 days too late
MOT expiry date	14 July 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-10-31
Last registration	2022-07-15
Complete history	See info



Registration #1	2007-10-31	18 mi
Registration #2	2010-10-26	10.022 mi
Registration #3	2011-02-18	11.225 mi
Registration #4	2012-02-13	17 mi
Registration #5	2013-02-15	24.684 mi
Registration #6	2014-02-17	30.507 mi
Registration #7	2015-02-17	32.697 mi
Registration #8	2016-02-10	35.180 mi
Registration #9	2016-09-12	36.623 mi
Registration #10	2016-09-15	36.623 mi
Registration #11	2017-09-13	39.887 mi
Registration #12	2019-05-29	51.377 mi
Registration #13	2019-05-29	51.377 mi
Registration #14	2019-05-29	51.377 mi
Registration #15	2019-05-29	51.377 mi
Registration #16	2019-05-29	51.377 mi
Registration #17	2019-05-29	51.377 mi
Registration #18	2019-05-29	51.377 mi
Registration #19	2019-05-29	51.377 mi
Registration #20	2019-05-29	51.377 mi
Registration #21	2019-05-29	51.377 mi
Registration #22	2019-05-29	51.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4018117