



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Blue
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-13
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-07
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	23
Total items failed	2

MOT #18 2023-09-08 08:42

MOT test number 252529014549

Result ✓ Passed

Next expiry date 2024-09-07

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge o/side front tyre worn on inside edge (5.2.3 (e))

Advice Rear Coil spring corroded o/side rear spring has corrosion (5.3.1 (b) (i))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge n/side front tyre worn on out side edge (5.2.3 (e))

MOT #17 2022-08-13 07:55

MOT test number 627202196995

Result ✓ Passed

MOT #16 2021-08-24 13:29

MOT test number 992267213539

Result ✓ Passed

**MOT #15**

2020-09-01 11:32

MOT test number

504303763353

Result

✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2019-08-28 13:33

MOT test number

177536868674

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

2019-08-27 11:05

MOT test number

533383885240

Result

✗ Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MAJOR Offside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

MOT #12

2018-08-23 14:54

MOT test number

384946721709

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2018-08-23 11:45**MOT test number** 713792726273**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #10** 2017-08-21 12:31**MOT test number** 537556299179**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-08-04 12:40**MOT test number** 614090039150**Result** ✓ Passed**MOT #8** 2015-08-19 11:33**MOT test number** 311485844969**Result** ✓ Passed**MOT #7** 2014-08-12 12:28**MOT test number** 717244624221**Result** ✓ Passed**MOT #6** 2013-08-06 13:54**MOT test number** 745218313299**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-08-05 13:28**MOT test number** 455737613247**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-08-29 12:48**MOT test number** 625592942266**Result** ✓ Passed**MOT #3** 2011-08-25 10:51**MOT test number** 186867631288**Result** ✓ Passed**MOT #2** 2010-08-17 14:07**MOT test number** 812809420233**Result** ✓ Passed**MOT #1** 2010-08-17 13:01**MOT test number** 620579020203**Result** ✗ Failed**Fail** Centre Rear Stop lamp not working (1.2.1b)



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
7 September 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-01
Last registration	2023-09-08
Complete history	See info



Registration #1	2007-09-01	7 mi
Registration #2	2010-08-17	26.154 mi
Registration #3	2010-08-17	26.154 mi
Registration #4	2011-08-25	35.488 mi
Registration #5	2012-08-29	45.185 mi
Registration #6	2013-08-05	53.149 mi
Registration #7	2013-08-06	53.154 mi
Registration #8	2014-08-12	64.152 mi
Registration #9	2015-08-19	75.848 mi
Registration #10	2016-08-04	87.115 mi
Registration #11	2016-08-04	87.115 mi
Registration #12	2016-08-04	87.115 mi
Registration #13	2016-08-04	87.115 mi
Registration #14	2016-08-04	87.115 mi
Registration #15	2016-08-04	87.115 mi
Registration #16	2016-08-04	87.115 mi
Registration #17	2016-08-04	87.115 mi
Registration #18	2016-08-04	87.115 mi
Registration #19	2016-08-04	87.115 mi
Registration #20	2016-08-04	87.115 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	6R30967
---------------	---------